APR 2 5 1995

MOISSIBABAOO

COMMISSION	1994 REMONUMENTATION PROG	RAM
	LAND CORNER RECORDATION CER	TIFICATE 모드 유
	Filing Requirement of Act 74, Mich.	P.A. 1970 미국장 교원들 및 은
For corners in Arbela Township Tuscola Loc	cated In: Corner Code ##	TIFICATE FILLING NO. PAGE VIRGINIA IN TUSCOL REGISTER
(County)	İ	9997 P
ू 1	10N R 7E M-10 R R	FOR RECORD PAGE NO. #101 #101 PM 4: 26 M. MOLAREN A COUNTY R OF DEEDS
2. Property Controlling S T in Section S T	R R	
Property in Sec. S T	R	Register of Deeds Stamp & File Number
		A B C D E F G H I J K L
5. Private Claims		2 6 5 4 3 2
		3
do hereby certify that under requirements of Pin lines 1 and 2 above were in conformance current manual of survey instructions of the Umanagement or by a decree of a Court of Law above were in conformance with the rules of the Court of Law; established, re-established, expressed below:	rvey on August 6, 19 9. A. 74, Michigan P.A. of 1970, the corner points men with regulations and rules therefore as required United States Department of the Interior, Bureau ound/or that the corner points mentioned in lines 3, 4 the Michigan Board of Land Surveyors or by a Decremonumented, re-monumented, recovered, four	tioned in the fi Land 7
NOTE: Not more than 4 corners, all in on this certificate.	the same town and range, may be recorded	1 11 12 31 32 33 34 35 3
A. Description of original monument an	d accessories and/or subsequent restoration	n:
1821 G.L.O. Notes Joseph Wampler, D.S. Set 1/2 mi. post Elm 6 N 64 1/2 W 6 ? 7 S 89 E 7	1959 Witness card from road surby R. J. Black, #3384. Found pipe. S15°E 84.56' spike in root of 185°W 55.27' face of tele. pole N83°W 34.62' spike in root of 8 North 80.71' W 1/4 cor. Sec. 30 Millington Township	3/4" form, filed on Page 28 D. T. Rowe, L.S. #1119 14" hickory Found 3/4" pipe e N85°W 55.01' nail & ca 8" oak
Section A continued on back		N45°W 42.70' nail & ca
B. Description of corner evidence found	d and/or method applied in restoring or rees	tablishing corner:
Also, found 1/2" pipe 1.75!	rock pile below road surface. southwest. Found no evidence 3/4" pipe as the proper position	n .
		•
Removed 3/4" pipe & placed 3	and accessories established to perpetuate lo	
N89°28'W 61.19' set T. C. Re N81°55'W 34.63' set T. C. Re N31°34'W 42.66' set T. C. Re	iron at base of steel fence poemon. tag & spike in S. face 13'emon. tag & spike in S. face 16'emon. tag & spike in E. face 24'eeel post (road side reflector)	hickory. oak. oak.

Signed by Date APPROVED Surveyor's Michigan License No. _

KENNETH D LAND SURVEYOR No. November 7,1994

NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 16
REVISED MAY 14, 16

Section A continued:

April 11, 1972 Survey by D. T. Rowe, L. S. #11192, recorded in Liber 1 of Surveys on Pages 552 & 553, Tuscola County records. Same object and accessories as shownon L. C. R. C., Page 28, Arbela Township.

May 13, 1976 Survey by D. T. Rowe, L. S. #11192, recorded in Liber 461 on Page 179, Tuscola County records. Same object and accessories as shown on L. C. R. C., Page 28, Arbela Township.

June 1, 1994 Survey by Barbara N. Snyder, P. S. #36001, recorded in Liber 660 on Page 202, Tuscola County records. Found 3/4" pipe. N83°W 34.00' face 16" tree

N45°W 42.50' face 20" oak West 33' "T" iron

S87°E 17.63' sign post

