## SURVEY & REMONUMENTATION

FEB 08 2001



SECTION

## 2000 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Elling Requirement of Act 74 Mich

Filing Requirement of Act 74, Mich. P.A. 1970


RECEIVED FOR RECORD
LIBER NO. PAGE NO.
FILE NO. PAGE NO.
00 DEC 19 PH 1: 34
GARY-MEYLEN TUSCOLA COUNTY RESISTER OF DEFOR

4. Lot No. \_\_\_\_\_\_, Recorded Plat

5. Private Claims

I, <u>Kari M. Lohela</u>, in a field survey on <u>October 26</u>, 20 <u>00</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

1822 G.L.O. NOTES, FLETCHER, D.S., SET CORNER TO SECS. 13, 14, 23 & 24.

NUMEROUS SUBSEQUENT SURVEYS CITED IN 1999 REMONUMENTATION LCRC, P. 112 VASSAR TWP.

1999 REMONUMENTATION LCRC, P.112 VASSAR TWP., DUNTON, PS 23503, SET 5/8" BAR AND BRASS CAP STAMPED K-7, T11N, R8E, IN MON. BOX.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BRASS CAP K-7 AND BAR ENCASED IN CONC., LAYING IN DITCH EAST OF FORMER POSITION.

ALSO FOUND ¾" BAR IN MONUMENT BOX ON CENTERLINE OF SHERIDAN ROAD. RECOVERED ALL 4 ACCESSORIES FROM 1999 REMONUMENTATION LCRC, SECTION C., WHICH INDICATES THAT POSITION OF ¾" BAR IS WITHIN ๑٠١' OF POSITION OCCUPIED BY FORMER CORNER K-7.

RESECTED POSITION OF CORNER K-7 FROM RECOVERED ACCESSORIES.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

RAISED ¼" BAR WITH ½" BAR AND STANDARD BRASS CAP STAMPED K-7, T11N-R8E. ENCASED BAR AND CAP IN CONCRETE IN EXISTING MONUMENT BOX.

N30°E, 87.41' EXPOSED SW REROD IN TOP OF CONC. R.O.W. MARKER
EAST, 34.54' FOUND REMON. TAG & NAIL OVER MSHD TAG IN N. FACE OF UTILITY POLE
WEST, 60.02' FOUND REMON. TAG & NAIL OVER MSHD TAG IN N. FACE OF UTILITY POLE
S20°E, 103.12' FOUND REMON. TAG & NAIL OVER NAIL IN SW FACE OF UTILITY POLE

SECTION

K-7

T11N-R8E

Signed by

Date 12/18/00

APPROVED BY TUSCOLA COUNTY **REMONUMENTATION PEER GROUP** 

Surveyor's Michigan License No. 44784

K-8 🚯

12 1/3/2000

KARI M. LOHELA
PROFESSIONAL
SURVEYOR
NO.
44289
PESSIONAL
PESSIONAL
MILITARIA
MILITARIA APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 199 K-6 SECTION 13 T11N-R8E 2000 LOHELA 94'22'08" SAGINAW 1822 FLETCHER 2643.3' 1898 FELTON 2689' 1995 GRAVLIN 2691.04' 1999 EMERY 2691.08' 2000 LOHELA 2691.13' ROAD 1995 GRAVLIN 84\*49'24" 1999 EMERY 84\*49'08" 2000 LOHELA 84\*49'21" SECTION 24 T11N-R8E