

DEC 07 1994

COMMISSION

1994 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

For corners in KOYLTON TOWNSHIP

	TUSCOLA (County)		Located In:	Corner Code ##				2	[™] >:	. *	ω,	75	İ) FUX	, 1
1.	Public Land Survey		T <u>11N</u> R111 TR_					0 1 0 0	VELLY VINDO	Xc1 3327	PH 2: 2	7072	_PAGE NO	REC	7
			T R T R						=	kas	O .	8	0	ć	:
2.	Property Controlling	s	T R									•	•		
	in Section	S	T R												
3.	Miscellaneous	S	T R		}	Regist	er o	f De	eds S	stan	10 &	File	Nur	mbe	r
	Property in Sec.	S	T R	~ ···											_
	Lot No.	Racordor	t Diat	,											
							A	ВС	D	E f	F G	Н	1 ,	J K	L.
Ψ.	Titalo Ciamo					2	_	;	5	└ ┆	. 4] 3 _	\perp	2-	
						3		\perp	\perp		_		丄		
						4	_	,	_	<u></u>		_ _10_	⊥,		·
ı, <u>L</u>	I Lionel Roy Emery in a field survey on June 20 19 94								Ľ	ĹĬ		Ĭ.	<u>L</u>		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned									17				L,		
			_	ns and rules therefore as req		7	Ϊ́		,,, 	Γï	\top	_,; 	Γ	ï	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5						8						I	T.		
	-			oard of Land Surveyors or by a	•	9	I ï	,	20	21	-	22 	1-2	23	7
		re-establi:	shed, monumented,	re-monumented, recovered	i, lound as	_							1		
•	ressed below:	•				10 11	l j	ا—	29 I	1-2E	+	-27-	 2	6-	— ₹
NOTE: Not more than 4 corners, all in the same town and range, may be recorded										H	\dashv	+	+	\vdash	
	on this certificate).				12	-3	1	3 2	3/3	;	34	+3	15-	3
	monadation of evicinal		-t	a and far authorau ant reato	untinn.	13	Ш			 _				ļl	
	· -			s and/or subsequent resto							_ ,		^ ~	4	
18	34 (Gov't. Land Hemlock 10 N3		Notes) Harvey	y Parke, D.SSet	quarter s	sect1	lon	po:	st-	В.	ASi	a II	2 S	4W	43
19	72 (Survey -Libe	rlof	Surveys, page East 33.0' "	e 349) David T. Row T" iron; S80°W 30.5	re, P.S. 1 56' PK na:	11192 il in	2 – s n Ar	set nch	or p	ir ost	:on-	- Na Wes	450 t 3	E 1 3.0	5. ''
19		r2 of S	Surveys, pages	s 20 and 21) David	T. Rowe,	P.S.	. 13	119	2 –	san	ne i	mar!	ær	an	ıd

above— Liber 1 of Surveys, page 349.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found "T" iron; found no accessories remaining; found remains of fence corner post and braces East side of road.

1972 (Land Corner Recordation Certificate) David T. Rowe, P.S. 11192 -Found pieces of wood &

charcoal 1.5'+/- under rd. Raised with "T" Iron. Accessories same as shown in 1972 Survey-

accessories as above Survey except distance to "T" iron East shows as 23,0'

Accepted found "T" iron as marking original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Removed "T" iron and replaced with Standard Tuscola County Concrete Monument w/ 2" Brass Cap stamped M10 T11N / R11E

N65°E, 45.15' T.C. Remon. tag in NW face of 9" Apple tree S65°E, 25.60' T.C. Remon. tag in SW face of 2" Ash S40°W, 17.11' Set 5/8" diameter reinforcing rod

N400W, 14.87' Set 5/8" diameter reinforcing rod

Surveyor's Michigan License No. 24593

Date Aug. 31, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1 REVISED MAY 14, 1 REVISED JAH . 1

ROY EMER'

N0

