1995 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Denmark Township Tuscola (County) Located In: Corner Code =## 1. Public Land Survey T <u>12N</u> R <u>7E</u> T _____ R ___ __ R . R 2. Property Controlling ___ R __ ___ T ____ R _ in Section Miscellaneous _ T R _ Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat ___ 5. Private Claims _ 1. Kenneth D. Dunton, in a field survey on ___ August 20 _ , 19 _95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented recovered found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. Description of original monument and accessories and/or subsequent restoration: Feb. 19, 1834 G.L.O. Notes Nov. 26, 1979 Survey by Kenneth D. Dunton, R.L.S. #23503 Orange Risdon, D.S. recorded in Liber 508, Page 842, Tuscola County Records. Set 1/2" rod and cap by single proportion method. NO2°E 156.67' p.k. nail in p.p., South 0.8' N. edge Set 1/4 Section Post to Sec. 35 White Oak 22" N46W 20 Links 20' wide pavement, NW 16.5' W. end conc. drive culvert, NE 27.8' E. end conc. drive culvert. White Oak 18" N42E 48 Links May 8, 1980 Act 74 form by K. D. Dunton, R.L.S. #23503 Section A continued on back of this form. Filed on Page 51 Denmark Township. Data same as Survey Liber 508, Page 842.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" rod & cap #23503 and accepted as the proper position of Corner J-13. SURVEY & MONEY THE PROPERTY DEC 11 1995 COMMISSION C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Removed rod and placed concrete monument with standard brass cap stamped Corner J-13, Tl2N-R8E. Placed monument box over monument. N48°21'W 16.52' chiseled notch atop W. end of 38' of 18" conc. drive culvert. N67°03'E 27.73' chiseled notch atop E. end of 38' of 18" conc. drive culvert. NOO°45'E 156.59' placed T. C. Remon. tag & spike above P.K. nail found in W. face p. pole. STATE OF MICHIGAN South 1.1' North edge of newer 20' wide asphalt road edge. South 0.3' North edge of old asphalt pavement below newer overlay. 公 KENNETH D. 4 **冷** DUNTON **LVMD** SURVEYOR Date Signed by -NO.

CAN STATE BOARD OF LAND SURVEYORS: JAN. 28, 1971
GEVISED MAY 14, 1975
GEVISED MAY 14, 1983 **APPROVED** 23503 Surveyor's Michigan License No. _ REVISED MAY 14, 1975

Section A continued:

May 29, 1984 Survey by B. D. Ferguson, R.L.S. #26454 of Hammond Engineering, Liber 541, Page 1022 & 1023, Tuscola County Records.

No mention of object found or set or accessories.

