SURVEY & REMONUMENTATION

MAR 0 5 1998

1997 REMONUMENTATION PROGRAM

RECEIVED FOR RECORD
LIBER HO. PAGE NO. #40
FILE TIO.

FILE	110	
111	Part	 100 11

LAND CORNER RECORDATION CERTIFICATE 97 107 -5 Pil 4: 02 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION Swinship	
Tuscola Located In: Corner Code #	Turbot A County
1. Public Land Survey <u>T12N R 10E</u> <u>C-13</u>	The tracking bridging
T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
5. Private Claims	2 6 5 4 4 3 - 2 1
Kenneth D. Dunton, in a field survey on Sept. 6, 1997 do he requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 conformance with regulations and rules therefore as required in the current manual of surv. United States Department of the Interior, Bureau of Land Management or by a decree of a that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, found as expressed below:	reby state that under 4 7 8 9 10 -11 12- and 2 above were in ey instructions of the Court of Law and /or 6 18 17 16 15 14 13- rules of the Michigan
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	
on this certificate.	10 - 30 - 29 - 28 - 27 - 2625 - 11
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restored	pration:
Hemlock 10" N78°E 16 1/2 links. FebApr. 1963 M. Chief. 3/4" pipe. North 51.13' fe. post, N35°W 6 Sept. 5, 1968 M.S.H.D. witness card, R. Fosdick, Srt. edge metal @ sta. 166+00, S45°W 101.50' to corrt. edge metal @ sta. 165+93 (pave. joint). Oct. #21559. 1" pipe - MSHD. Same accessories as 1968 L-608, P-1029 by Dunton, L.S. #23503. No mention of survey L-506, P-1119 & 1120 by Rowe, L.S. #11192. B. Description of corner evidence found and/or method applied in restoring of Second 3.1 piges in place and the second s	GO.99' fe. post, S50°E 49.60' 28" Elm. Gurvey Chief. l" pipe. N50°E 14.40' to fen. post clear vision, N10°W 11.90' to 10, 1975 survey L-456, P-422 by Beck, L.S. witness card. March 22, 1989 survey of object found or accessories. June 2, 1980 Same object and accessories as L-456, P-422. Treestablishing corner:
Found 1" pipe in place and two accessories that in same position as the 1968 witness card. Accepted corner.	ldicate that the corner found is in the life in the li
C. Description of monument for corner and accessories established to perpete Removed 1" pipe and placed concrete monument with North 112.79' chiseled "+" atop conc. R/W marker. North 23.75' centerline E-W conc. pavement, M-46. N35°W 14.55' rt. edge conc. pavement @ sta. 166+00 S45°W 101.42' angle iron post @ NW end clear visio N89°E 88.93' fnd. 1" pipe. Note: Either pipe may East 88.93' fnd. 1" pipe.	standard brass cap stamped C-13, T12N-R10E. . n fence.
Signed by	Date 10-27 KENNETH D. * LAND LAND LAND
APPROVED ARE	SURVEYOR No. 23503 MAPPROVED BY MICHIGAN STATE BOARD OF TROPESSIONAL STATE BOARD OF TROPESSION PREVISED JAN. 28, 1971 REVISED JAN., 1883 REVISED OCT., 1995

T12N-R10E __ Sec.32 1834 Parke 2640' 1963 wit.card 2639.45' 1997 Dunton 2640.45' 1834 Parke 2640' 1963 wit.card 2650.65' 1997 Dunton 2651.01' B-13 Township Line Apparent Cor. C-1,Tl1N-R10E 1997 Dunton 88.93' Fnd. 2-1"pipes 1.37'apart N&S. Sec. 6 · TllN-RlOE Sec. 5