## SURVEY & REMONUMENTATION

MAR 0 5 1998

## 1997 REMONUMENTATION PROGRAM

SECTION	LAND (	CORNER RECORDATION	CERTIFICATE		SILE LIBE P
For corners in Kingston	Filina	Requirement of Act 74, Mid	ch. P.A. 1970		II III
Tuscola (County)	Located in:	Corner Code #			CEIVED
1. Public Land Survey	T <u>12N</u> R <u>11</u> T R T R T R	E		- 35 N	PAGE NO.
Property Controlling in Section     Miscellaneous     Property in Sec.	S TR S T R S T R S T R		Regist	O P	
4. Lot No, Recorde	d Plat			,	
5. Private Claims			1 A B 6	D E F G H	I J K L M
requirements of P.A. 74, Michigan F conformance with regulations and rule United States Department of the Interthat the corner points mentioned in Board of Land Surveyors or by a recovered, found as expressed below	es therefore as required in fior, Bureau of Land Managines 3, 4 and 5 above were Decree of a Court of La	pints mentioned in lines 1 and 2 abo the current manual of survey instruct gement or by a decree of a Court of L e in conformance with the rules of the	ions of the aw and /or 6	-8 - 9 - 10 -17 - 16 - 15 -20 - 21 - 22	) - 11 - 12 - 13 - 14 - 13 - 23 - 24
NOTE: Not more than 2 corners on this certificate.	, all in the same town an	d range, may be recorded	9 10 30	29 —28 —27	25 25
•			12 - 31	-3234	35 36
A. Description of original monun	nent and accessories a	nd/or subsequent restoration:	13		
1" iron. N45°E 75.2 1971 two L.C.R.C. fo 19.87' centerline M- post. Oct. 14, 1971 forms, Pages 1 & 5.	20' p. pole, N2 20' p. pole, N2 20rms, pages 1 & -46, West 4'± co 1 survey L-1, P- Eeb. 4, 1972 survey L-1, P-239 &	Set post corner Sect July 1963 M.S.H.D. w 5°W 74.99' t. pole, 5 5 filed by Rowe, L.S enterline Phillips Ro -239 & 240 by Rowe, L rvey L-1, P-366 & 367 240. June 12, 1981 dapplied in restoring or reestabli	itness card, H. \$30°W 65.15' t. 5. #11192. Four bad ext., East : S. #11192. Sa ' by Rowe, L.S.	G. McManus, pole. Sept. nd l 1/4" pip 27.02' w'ly. ame object as	Survey Chief & Oct. De. North guard rail L.C.R.C.
Found 1" pipe in pla position as the 1971 corner.	ce and one acce L.C.R.C. forms	essory that indicates . Accepted 1" pipe	the corner for as the best evi	ind is in the dence of the	same original
·					
C. Description of monument for a Removed 1" pipe and T12N-R11E. Placed m North 19.87' E-W cen S80°E 27.62' set T. S86°W 6.11' fnd. 1" N88°W 264.52' fnd. 1' N89°W 270.07' fnd. 1,	placed concrete onument box ove terline conc. p C. Remon. tag & pipe. " pipe at appar	e monument with stand er monument. avement M-46. spike atop new guar	ard brass cap s d rail post.	rner: tamped cap C-	-13,
Signed by Surveyor's Michigan License No.	DA Z 23503	Date	. //-/0 - \$	KENNETH I	<del>*</del>
	APPROVED		BY MICHIGAN STATE BOARD	SURVEYOR No. 23503 PROFESSIONES	EXONS JAN. 28, 1971 EXISTO MAY 14,1975 AREVISED JAN. 1983
		atral		******	REVISED OCT., 1995

Section A con't from front of form:

Same object and accessories as survey L-1, P-366 & 367. Aug. 22, 1985 survey L-553, P-365 by Emery, L.S. #24593. Same object and accessories as survey L-516, P-827. March 28, 1990 survey L-615, P-692 by Gravlin, L.S. #23510. Same object and accessories as survey L-553, P-365. July 6, 1994 survey L-667, P-983 & 984 by Field, L.S. #37276. Found 1" pipe. N89°W 270.03' fnd. 1/2" rod, S86°W 6.10' fnd. 1" pipe, N88°W 264.50' fnd. 1" pipe, North 19.91' centerline joint in conc. pave.

