MAR 02 1999

RECEIVED FOR RECORD

LIBER	NOP	AGE	NO.
	セクハ	-D.1	

1998 REMONUMENTATION PROGRAMFILE NO FILE COLUMNIA INFO LAND CORNER RECORDATION CERTIFICATE 98 DEC 18 AM 10: 09

Filing Requirement of Act 74, Mich. P.A. 1970

TUSCOLA Located in: Corner Code # T14N R 9E 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat	
5. Private Claims		

OCT. 22 , 19 $\frac{98}{}$ do hereby state that under in a field survey on _ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	<u>A</u>	В	С	D	Ε	F	G	H	I	J	K	L	١
				T	Т	Т		T	-	T	T	T	
2	 	6-		\$-	╌	- 4-	+	— j	+	- 2 -		- į-	
3	-	4_	+-	+	+-	- -	4	 	╄-	_	+	4	
4	⊢	7-	-	8-	-	ا - 9_	+	-10-	-	·11–	4	 -12	_
5	H	-	╀	┿-	4	+	+		\vdash	╀	-	+	_
6	<u> </u>	 1 ,8 —	-	 17-	╀	 -1,6		 -1 <u>5</u>	1	 14	\perp	 -13-	
7			\perp	╀	_	╀	\bot		<u> </u>	\bot	_	4-	
8	L	19	\downarrow	 20	╀	-21_	-	-22-		23_	╀	 -24-	
9	L	ļ <u>.</u>	1	_	$oldsymbol{\perp}$	\downarrow	_		╙	\perp			
10	L	30	\vdash	 29—	-	-28-	+	-27	ـ	2 <mark>6</mark> -		-25-	
11	L	┢	+	+	╁		+	_	-	╀	+	+	
12	Ļ	31—	 :	32_	1	.33-	-	_34	\vdash	ا 35	- -	-36-	
13		L.	<u></u>		1_				<u> </u>			Ĺ	

A. Description of original monument and accessories and/or subsequent restoration:

1835 GLO NOTES (PG. 136): HERVEY PARKE, DEP. SUR. SET QR. SEC. POST; B. ASH 11 S35W 18; HEMLOCK 7 N30W 34 (NO DATE)—COUNTY SURVEYOR'S "MINUTES OF SURVEY" (PAGES 108 AND 109) BY: (NO SURVEYOR'S SIGNATURE) SURVEY OF SECTION 12, T14N-R9E; EAST 1/4 CORNER- CEDER STAKE SET IN CROCKERY

1992 RECORDED SURVEY (LIBER 633, PAGE 505) BY: KENNETH D. DUNTON, P.S. #23503; FND. P.K. NAIL; N88*W 25.12' FND. SPIKE IN COR. POST; SOUTH, 9.0' CENTERLINE DRAIN EAST; S45°W 16.89' SET 1/2" ROD 1' WEST OF WEST EDGE OF PAVE.; S45°E SET 1/2" ROD 1' EAST OF EAST EDGE OF PAVE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 5/8" RE-ROD IN MONUMENT BOX TOGETHER WITH 3 ACCESSORIES SHOWN ON SURVEY IN SECTION A. ABOVE INDICATING FOUND RE-ROD TO BE IN SAME POSITION AS P.K. NAIL FOUND BY DUNTON IN 1992.

ACCEPTED FOUND RE-ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL GOVERNMENT CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: FITTED 5/8" RE-ROD IN MONUMENT BOX WITH STANDARD TUSCOLA COUNTY 2 IN. DIA. BRASS CAP

STAMPED M4 T14N R9E. -PLACED CONCRETE IN MONUMENT BOX. N66°E, 14.82 FT. SET 1/2" RE-ROD IN GRAVEL SHOULDER

S40°E, 16.91 FT. FOUND 1/2" IRON ROD IN GRAVEL SHOULDER S40°W, 16.87 FT. FOUND 1/2" IRON ROD IN GRAVEL SHOULDER

WEST, 25.08 FT. SET T.C. REMON TAG OVER FOUND SPIKE IN SOUTH FACE OF WOOD POST

NOTE: THIS CORNER IS COMMON WITH CORNER A 4 TIAN RIDE (ELMWOOD TOWNSHIP)

Signed by 24593 Surveyor's Michigan License No.

Date DECEMBER 1998

APPROVED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

LIONE

ROY EME AND BURVEYOR NO

SURVEY & REMONUMENTATION

MAR 02 1999

SECTION

