MAR 02 1999

1998 REMONUMENTATION PROGRAM

SECTION

LAND CORNER RECORDATION CERTIFICATE

RECEIVED FOR RECORD	
LIBER NO PAGE NOTE	7
FILENO. ELM WOOD	TWP

Filing Requirement of Act 74, Mich. P.A. 1970

98 NOV 20 AMII: LO

For corners in: ELMWOOD TWP.		,	Gnn	U-TY	Sola	لم	
TUSCOLA Located In: Corner Code #			TUS	P COLA (STER (COUNT	Y	
(County)					F DEED	S	
1. Public Land Survey			♥ √	↓ .			
2. Property Controlling S TR	Register of Deeds Stamp & File Number						
Property in Sec. S TR							,
	1	A B	D 6	E F G	H (JK	_ <u>L_M</u>
Lot No Recorded Plat Private Claims	2	1 5	5	4	3	2	<u> </u>
	3 4		8	9	10	11	12
1. JONATHAN M. FIELD , in a field survey on MAY 15 19 98 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in	ned 6	1	17	.16	15	14	13
In lines 1 and 2 above were in community with the United States Department of the Interior, Bureau of Land current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	nd 5 8	19	20	21	22	23	24
	as 10	1	29	28	27	26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.		2 31	32	33	34	35	36
	,						

Description of original monument and accessories and/or subsequent restoration: 1835 GLO; PARKE, D.S.; SET 1/4 SEC. POST; PINE 15 S30W 24 LKS., B. ASH 6 N7W 13 1/2 LKS. 1916 PRASCHAU; CO. DRAIN NOTES BK.25 PG.209; SHEBEON DRAIN CROSSES TWP. LINE AT SW COR. OF NW 1/4 SEC, 6 T14N-R10E

1958 CASE; CO. DRAIN NOTES BK.40 PG.391; SHEBEON DRAIN CROSSES TWP. LINE AT SE COR. NE 1/4 SEC.1 T14N-R9E

GLO NOTES FOR T14N-R11E IMPLY THAT THIS CORNER IS COMMON WITH A-2 T14N-R11E

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998 ROWE; FIELD, PS #37276; FND. NO EVIDENCE OF MONUMENT AT CORNER; REESTABLISHED CORNER POSITION BY SINGLE PROPORTION OF GLO DISTANCES; POSITION THUS REESTABLISHED FALLS AT APPROXIMATE C/L - C/L OF EXISTING DRAINAGE DITCH

ACCEPTED PROPORTION AS BEST REESTABLISHMENT OF ORIGINAL CORNER POSITION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-2 SET WITNESS CORNER (STD. REMON MONUMENT CAP STAMPED M-2 W.C. T14N R10E) 10.43' N. & 19.10' W. (SEE BACK OF THIS FORM FOR SKETCH)

WITNESSES FOR M-2 WITNESS MONUMENT

S61°E, 21.77' POSITION OF M-2

S49°E, 62.08' SET 1/2" ROD W/ CAP #37276

N07°E, 104.77' SET NAIL W/ TAG #37276 IN P.POLE

S07°E, 112.63' SET NAIL W/ TAG #37276 IN P.POLE

WITNESSES FOR M-2 (ACTUAL POSITION) N61°W, 21.77' SET REMON MON. FOR WIT. COR. S43°E, 41.00' SET 1/2" ROD W/ CAP #37276 N03°W, 114.82' SET NAIL W/ TAG #37276 IN P.POLE

N03°W, 101.31' SET NAIL W/ TAG #37276 IN P. POLE OF MICH

Signed Michigan License No. Surveyor's

Date

PROFESSIONAL SURVEYOR

JONATHAN M. FIELD

98 OARI**37278**D FORM APPROVED BY MIC

BO POPE WORD RI

<u>APPROVED</u>

NORTH

BAY CITY - FORESTVILLE ROAD

SURVEY & REMONUMENTATION

MAR 0 2 1999

SECTION