SURVEY & REMONUMENTATION

MAR 02 1999

SECTION

1998 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD LIBER NO._ -PAGE NO.#5 FILE NO. ELM WOOD

For corners in: ELMWOOD 1	rwp.	I			98	NOV	20 A	 M.11. 1	TWI
TUSCOLA (County)	_ Located In:	Corner Code #							
1. Public Land Survey	T <u>14N</u> R <u>10E</u> TR TR	M-12			, <i>v</i>	TUSCO	LA COL	HTY EEDS	1
Property Controlling S	TR TR TR TR TR		Register of Deeds Stamp & File Number						
4. Lot No, Record 5. Private Claims	ded Plat		1 2	A B	C D	E F	G Н 3	1 J H	LM
I. JONATHAN M. FIELD	. in a field surve	von MAY15 19.00	3 4 R 5	7	8	9	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded			ned 6	18	17	"16	15	14	13
			nd 5 8	19	20	21	22	23	24
			as 10	30	- 29	28	27	26	25
on this certificate.	rs, air in the same town a	and range, may be recorded	12	31	32	33	34	35	36 €

Description of original monument and accessories and/or subsequent restoration: 1835 GLO; PARKE D.S.; SET 1/4 SEC. POST; SUGAR 22 N24 1/2W 16 1/2 LKS., BEECH 11 S28W 30 LKS. 1987 HURON SURVEYING INC.; BROWN, P.S.#24588; SURVEY L.572 PG.330; FND 1/2" RE-ROD; EAST 42.18' NAIL S SIDE P/P, WEST 30.0' NAIL S SIDE 6" ELM, NORTH 47.65' NAIL S SIDE 10" APPLE

GLO NOTES FOR T14N-R11E IMPLY THAT THIS CORNER IS COMMON WITH A-12 T14N-R11E

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998 ROWE; FIELD, PS #37276; FND. 1/2" ROD ON C/L GRAVEL ROAD N-S; RECOVERED 3 PREVIOUS WITS. WHICH INDICATE THAT FND. ROD IS IN SAME POSITION AS 1987 SURVEY CITED IN SECTION A. ABOVE.

ACCEPTED FND. ROD AS A CAREFUL & FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-12 REPLACED FND. 1/2" ROD W/ STD. REMON. MONUMENT & CAP STAMPED M 12 T14N R10E WEST, 29.92' SET NAIL W/ TAG #37276 IN S. FACE 8" ELM

S85°E, 42.10' FND. NAIL W/ FLAG. IN S. FACE P.POLE N25°W, 47.58' FND. NAIL W/ FLAG. IN S. FACE 12" APPLE N20°E, 79.51' SET NAIL W/ TAG #37276 IN E. FACE 8" ELM

Signed by Date Surveyor's Michigan License No.

ORM APPROVED BY MICH

PROFESSIONAL SURVEYOR

JONATHAN M. FIELD

SURVEY & REPROMUMENTATION

APPROVED 10-12-98

MAR 02 1999

SECTION

