## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

|  |   |                        |  | <u>#</u>                                  |  |
|--|---|------------------------|--|---|--|
| FOR CORNERS OF   | •   | ATED IN-:              | CORNER CODE NUMBER   | 4   |  |
| 1. PUBLIC LAND   | SURVEY 27 T.  | 15 N. R. 8 E.          | <u>G-11, G-5</u>   |   |  |
| 2. PROPERTY CO   | ONTROLL-<br>SECTION,T   | N. E. W.               |  |   |  |
| 3. MISCELLANEO PROPERTY IN   |   | N. E. W. W.            |  |   |  |
| 4. LOT NO  | , RECORDED  | PI.AT                  | · · · · · · · · · · · · · · · · · · ·  |   |  |
| 5. PRIVATE CLA   | IMS   |                        |  | REGISTER OF DEEDS STAMP AND FILING NUMBER |  |
| I, Thomas G. Moran , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October , 1979 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on |   |                        |  |   |  |
|  |   | al a seminarion and/or | subsequent restoration.  |   |  |
| A. Description of original monument and accessories and/or subsequent restoration:  G-11 This corner was recovered and used in a survey by D. E. Craston January 27, 1870. Corner was recorded and iron rod placed by R. Black date unknown.   |   |                        |  |   |  |
| G-5 Th   | G-5 This corner was recovered by R. Black. Iron rod placed over wooden post.  |                        |  |   |  |
| <ul> <li>B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:</li> <li>G-11 Recovered iron rod placed 1" iron pipe with plastic cap 6" below gravel surface.</li> <li>G-5 Dug and found iron rod set on top of wooden post set 1"x 36" iron pipe with plastic cap 6" below surface.</li> </ul>  |   |                        |  |   |  |
| C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  G-11 1" iron pipe.  G-5 1"x 36" iron pipe.   |   |                        |  |   |  |
| N 45 <sup>0</sup> W<br>N 45 <sup>0</sup> E<br>S 33 <sup>0</sup> W  | 87.39' Power<br>88.04' Power<br>66.50' N.E. C<br>brick pumph<br>0' [ N-S Road | Pole<br>Pole<br>or.    | North 139.09' 8" As<br>N 66 <sup>0</sup> E 47.90' 4"<br>S 14 <sup>0</sup> W 68.50' 4"<br>East 13.0' £ Gravel | Ash<br>Ash                                |  |
| SIGNED BY  |   |                        | DATE   |   |  |
|  | MICHIGAN REGISTE  |                        |  | (SEAL)                                    |  |
| FOR STATE A  | ND UNITED STATE   | S AGENCIES:            |  | 35.40                                     |  |
| SIGNED BY  |   | FOF SURVEY PARTY       | DATE   | 1.0.20                                    |  |
| APPROVED A   | ND SIGNED BY  | 2 . I /T /             | LAND SURVEYOR  | (SEAH) 2 YOR NO 25050                     |  |
|  |   |                        | 25260  | WXX                                       |  |

PAGE

5

FORM APPROVED BY MICHIGAN STATE BOARD OF