4 35 PM '98

Dec 28

SECTION	Coa	24	

LAND

CORNER	R RECORDATION CERTIFICATE	•	·	, , ,

PINE GR	OVE TWP Filing Require	ment of Act 74, Mich. F	P.A. 1970 May On Mail	ş
For corners in AN BUREN	Located In:	Corner Code #	VAN BUREN CO	~
Public Land Survey	T 1S. R 13W. T	M-9		1 1050RVEY
2. Property Controlling	S T R		<u> </u>	1010
in Section	STR	*	1 / Min 5 / M/ ii / A/O	රා 19
3. Miscellaneous	S T R			<u></u>
Property in Section	S T R		Register of Deeds Stamp & File Number	ri
	Recorded Plat		A B C D E F G H ! J h	S) KG L
do hereby certify that under req in lines 1 and 2 above were in c manual of survey instructions Management or by a decree of 5 above were in conformance	in a field survey on December guirements of P.A. 74, Michigan P.A. conformance with regulations and rules of the United States Department a Court of Law and/or that the consults with the rules of the Michigan Boalblished, re-established, monumented.	of 1970, the corner points me les therefore as required in the int of the Interior, Bureau on her points mentioned in lines a and of Professional Surveyors	nentioned 6 18 17 16 15 14 ne current 7 0f Land 8 19 20 21 22 23 s or by a ed, found 10 30 29 28 27 26	-24- -25-
NOTE: Not more than 4 cor on this certificate.	rners, all in the same town and r	ange, may be recorded	11	36

Description of original monument and accessories and/or subsequent restoration:

1827 - William Brookfield, D.S., North on East line of Sec. 25 a distance of 80 chains (5280.00') and set post corner, 14" Wh. Oak S. 17° W. 15 lks. (9.90'), 14" Wh. Oak N. 28° W. 35 lks. (23.10'), Distance West is 80.89 chains (5338.74'). 1901 - W.H. Goss, D.C.S., Found old stake and stump of witnesses-Renewed with a black ash stake. Distance West is 40.465 chains (2670.69'), to North quarter post (old stake and witnesses set 1" gas pipe) and continued 2670.69' to Northwest corner for a total of 5341.38'.

No date - County Drain Office, Drain crosses line 9.70 chains (640.20') South of the Northwest corner, Section 25.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No corner marker found. Position of corner established by measuring between the two closest Van Buren County Section corners North and South, said corners being a 11/2" pipe found at the East quarter corner, Section 13 (per 1901 W.H. Goss, D.C.S.) and a 11/2" pipe found at the East quarter corner, Section 25 (per 1915 W.H. Goss, D.C.S.). The distance measured between said corners is 10,502.97 feet. Divided this measure into 4 equal half miles (10,502.97' \div 4 = 2625.74') and placed a 30" slimline Standard Van Buren County Remonumentation Monument at Southeast corner, Section 24 at 2625.74 feet North of said East quarter corner, Section 25. Monument placed is on a straight line between said East quarter corner, Section 13 and said East quarter corner, Section 25. Position of monument placed was ratified by the Van Buren County Remonumentation Peer Group on December 9, 1998.

POINT OF INTEREST: Historic survey notes for Kalamazoo County indicate finding that some of the existing fences for property in Alamo Township had been placed on the Van Buren corners.

C. Description of monument for corner and accessories established to perpetuate locating the corner:

Position of monument placed as above described is accepted as a careful and faithful reestablishment of the position of the original corner, Accessories:

Nail & Tab in Quad Ash N. 10° W. 38.77' Nail & Tab in 12" Ash N. 85° W. 11.56' Nail & Tab in 8" Ash South 20.32" Nail & Tab in 32" Maple East 60.001 2.5' West of West edge of creek

In line with fence to East and 4' North of centerline ditch to the West

MICH 3 F ALLEN H McMACHEN PROFESSIONAL SURVEYOR No. 16935 PROFESSIONAL

Signed by

Surveyor's Michigan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983