

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Van Buren _____ <small>(County)</small>	Located In:	Corner Code <i>##</i>
1. Public Land Survey	T 1S R 16W	G-1
	T 1S R 16W	G-2
	T 1S R 16W	F-1
	T _____ R _____	_____
2. Property Controlling in Section	S T _____ R _____	_____
	S T _____ R _____	_____
3. Miscellaneous Property in Sec.	S T _____ R _____	_____
	S T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4	3		2		1			
3													
4	7		8		9	10		11		12			
5													
6	18		17		16	15		14		13			
7													
8	19		20		21	22		23		24			
9													
10	30		29		28	27		26		25			
11													
12	31		32		33	34		35		36			
13													

I, Donald L. Bissell, in a field survey on May, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-1 Found 1/2" re-rod in pavement	G-2 Found 5/8" iron rod	F-1 Found 1/2" iron rod 1' North of 9 pavement
---	----------------------------	--

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-1 NE Cor. Sec. 4, T1S, R16W Found: 1/2" re-rod in pavement Phone Pole SW 41.3' Street Sign SE 43.5' 8" Wild Cherry N-W 68.15' 6" B. Walnut N46°E - 63.3' 5" B. Walnut N64°W - 105.55'	G-2 E 1/4 Cor Sec. 4, T1S, R16W Found: 5/8" iron rod No Witness Available Tree row going E across ditch unable to use for Witness.	F-1 N 1/4 Section 4, T1S, R16W Found: 1/2" iron rod 1" N 9 pavt. Allegan Corner E 84.26' 9 phone ped. E-SE 86.8' 9 phone ped. S 35.0' 42" Willow N08°W - 38.2' E end C. S. P. 40.0' under dr.
--	---	--

Signed by Donald L. Bissell Date _____
 Surveyor's Michigan License No. 18655

