Surveyor's Michigan License No.

FILED

W. 1/4 coline I JOSec. 29 LAND CORNER RECORDATION CERTIFICATION	ATE DEC 17 3 05 PN 197
Filing Requirement of Act 74, Mich. P.A. 19	970
For corners in Almena Township Van Buren (County) Located In: Corner Code #	Mark a South
1. Public Land Survey T _2S R _13W T R T R T R	O101 10SURVEY
2. Property Controlling S T R	Liber 5 Page 66 \$
Property in Section ST R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K
	3
Allen H. McMachen , in a field survey on December 5 , 19 97	4 7 10 11 1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current	
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	7
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found	
as expressed below:	10 30 29 28 27 26 2
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	12 31 32 33 34 35 33
A. Description of original monument and accessories and/or subsequent restoration:	131
1830 - G.W. Harrison, D.S., Set quarter Section post, 30" Pine S. 15° W. 11 lks., 18" Pine N. 36° 30' W. 12 lks. 1886 - A.A. Fosdick, C.S., Used stone most of the time, 8" Pine N. 33° W. 94 lks., 3' Maple N. 53° E. 62.25 lks. 1951 - T.A. Smith, C.S., "Found 1½" iron pipe", 20" Black Oak N. 80° W. 23.8', 18" Walnut N. 30° E. 76.5' 1971 - W.Q. Smith, Found 1½ pipe, 30" Oak West 23.45'	., "Found 1½" pipe"
B. Description of corner evidence found and/or method applied in restoring or reestablis	hing corner:
Found $1\frac{1}{2}$ " pipe 8" below gravel road surface in centerline of 32nd Street and in center witness. Dug around pipe and found pipe ringed with brick and stones beginning ± 2 ' of pipe (pipe is 3.7' long). Continued digging ± 3 ' below bottom of pipe to ground water corner. Found $1\frac{1}{2}$ " iron pipe was ratified by the Van Buren County Remonumentation	below top of pipe and extending to bottom
accord Va	atified by Peer Group in dance with P.A. 345 of 1990 n Buren County Surveyor
Date <u>&</u>	D. R.S. 12/10/97
C. Description of monument for comer and accessories established to perpetuate locating	ng the position of the corner:
Found 1½" iron pipe is accepted as the best available evidence of the position of the corner. Replaced found pipe with a standard Van Buren County Remonumentation monument and mon. box over, Accessories:	ALLEN H.
County Remonumentation monument and mon. box over, Accessories: Nail & Tab (existing) in South side 10" Twin Pine S. 35° E. 74.10' Nail & Tab (existing) in North side 18" Oak S. 55° W. 33.00' Nail & Tab (existing) in South side 24" Oak N. 75° W. 23.83' Nail & Tab (existing) in West side 36" Oak N. 15° W. 49.08'	McMACHEN PROFESSIONAL SURVEYOR NO.

REVISED JAN., 1973