## **Van Buren County Remonumentation Program**

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
West Quarter Corner 31

For corners in Bangor Township West Quarter Corner 31							
_	Van Buren (County)	Located In:	Corner Code #				
	Public Land Survey Property Controlling	T <u>2S</u> R_ TR_ TR_ TR_ STR_					
	in Section Miscellaneous	S TR_ S TR_					
	Property in Sec.	S TR_			Register of Deeds S	tamp & File Number	
	Lot No , Reco Private Claims			<del></del>	ABCDEF	G H I J K L	
<b>J</b> .	Pilvate Ciaillis				2 6 5 4	3-21	
	0.00		5100 40.07		3		
i, _	Gary C. Bilow uirements of P.A. 74, Michig	an P.A. of 1970, the come	4 - 7 - 8 - 9 -	10-11-12			
Un	ted States Department of the	Interior, Bureau of Land Ma	d in the current manual of surve anagement or by a decree of a C	ourt of Law and /or	6 18 17 16	15 14 13	
Во	ard of Land Surveyors or b	y a Decree of a Court of	were in conformance with the ru f Law; established, re-establish	nes or the Michigan ned, monumented,	7	<del> - - - - - -</del>	
	overed, found as expressed b				8 19 20 21	222324-	
NC	on this certificate.	THEIS, AM IN THE SEITHE CONTI	n and range, may be recorded	•	10-30-29-28-	27 26 25	
					11		
					1 31 32 33	35 36	
A. Description of original monument and accessories and/or subsequent restoration:							
	A12, Comer not established by General Land Office Survey. In April, 1872, County Surveyor AJ Pierce set a stake and stone for the corner and notes a distance of 24 links north to the standard corner, which is ½ of the GLO falling at the section corner north. Pierce witnessed a Bitternut 10, N75 2/3° E, 27 ½ links and measured the half mile north at 39.59. In 1903, Surveyor JS Haines calls for an iron witnessed to a Bitter Hickory 4, N75 2/3° E, 27 ½ links. Haines shows a distance of 39.675(2618.55') for the half miles north and south and measures .235 chain(15.51') N to the Covert corner. In a 1992 survey, Surveyor BJ Andress, Jr. calls for a ½" iron with cap and measured the half mile south at 2618.16. Andress witnesses a nail in SW side PP, WNW, 57.90; PK in NW side 4" gate post(N post), SE, 48.76; a ½" pipe, NNE, 22.61(15' +/- E of centerline, trav. Pt); center of blacktop, W, 4 +/						
₿.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
	A12, Found 1/2" rebar an	d all of Andress' witnes	sses. Accepted rebar for o	orner location.			
	PEER GROUP OF SI	URVEYORS AT A ME RNMENT SURVEYO	EETING HELD MARCH DRS. THIS MONUMEN	26, 1997. THIS	I COUNTY REMONUME S POSITION WAS NOT D AS THE BEST AVAIL	ESTABLISHED	
C.	Description of monument	t for corner and accesso	ories established to perpetua	te locating the po	esition of the corner:	OF MICHICAN	
S 36° E, 48.75, PK nail in N gate post S 82° E, 92.93, nail and tag in 14" Walnut N 70° W, 57.90, nail in pole N 31° E, 22.65, ¾" pipe(Andrus trav pt) North, 16.10, Harrison monument at East Quarter Corner section 25, Covert Township West, 5 feet, centerline 76 <sup>th</sup> Street							
Sic	ned by Cia	y C. Bil	ω	Date	November 19, 1997	, <u> </u>	
Signed by							