## SURVEY & REMONUMENTATION

JAN 1 4 1998

## SECTION

## **Van Buren County Remonumentation Program**

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Covert Township	Quarter Corner 24,25		
Van Buren Located In:	Corner Code #	FILED	
1. Public Land Survey	7W <u>L9</u>	DEC 11 4 33 PM '97	
2. Property Controlling S T R IN Section		Mark Comily  VAN ELINEN  LIBER 5 PAGE 19  Register of Deeds Stamp & File No.	ımber
4. Lot No, Recorded Plat			
5. Private Claims		1 A B C D E F G H I J 1 2 - 5 - 4 - 3 - 2 - 2 - 2	K L
I, <u>Gary C. Bilow</u> , in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner conformance with regulations and rules therefore as required in United States Department of the Interior, Bureau of Land Man that the corner points mentioned in lines 3, 4 and 5 above we Board of Land Surveyors or by a Decree of a Court of Linecovered, found as expressed below:	points mentioned in lines 1 and 2 above were in in the current manual of survey instructions of the lagement or by a decree of a Court of Law and /o ere in conformance with the rules of the Michigan	n 5   1   1   1   1   1   1   1   1   1	121324
NOTE: Not more than 2 corners, all in the same town a on this certificate.	ind range, may be recorded	9 10 30 29 28 27 26 11 12 31 32 33 34 35	25
Description of original monument and accessories		13	
L9, Post set by US Deputy Surveyor GW Harriso 12 links-half miles measured 40.165 chains(2650 the Hemlock witness. Goss measures the half m found iron" and measures the half mile west at 30 and witnessed a pear tree N20°+/-E, 53.5. Smith Middleton reports finding a plow point and pipe, washer in 10" Cherry, SW, (no distance). Survey in pole, N15°W, 46.75; PK nall In 6" Cherry, Sout 2666.65 east and 2623.40 west.	0.89). In May, 1902, County Surveyor V nile east 40.41 chains(2667.06). In 1906 9.90 chains(2633.4'). In March, 1931, C h measured the half mile west 2623.8. I Middleton witnesses are a tack and was y notes from surveyor AW Howard recife	VH Goss calls for a post and plow point and Goss notes County Surveyor TA Smith found the plow p n his 1972 LCRC at Liber 1, page 424, DA sher in PP, NNW, 46.82 and a tack and	d point
B. Description of corner evidence found and/or method	od applied in restoring or reestablishing or	orner:	
L9, Found ½" rebar inside ¾"x18" pipe at surface perpetuation of the position of the original corner	e. At 30" deep found ½" x18" pipe. Acc	cepted lower pipe as careful and faithful	
THIS GOVERNMENT MONUMENT WAS REMONUMENTATION PEER GROUP OF S ACCEPTED AS A CAREFUL AND FAITHFU	SURVEYORS AT A MEETING HELD	FEBRUARY 26, 1997, AND IS	
C. Description of monument for corner and accessorie	es established to perpetuate locating the p	osition of the corner	
L9, Replaced pipes with 20" Harrison monument S 34° E, 37.89, nail in 6" Red P S 35° W, 38.19, nail in 6" Red F N 13° W, 47.46, nail and tag in Corner is 1' North of center of 4	inside a monument box. Witnessed: line Pine pole	GARY C.  BILOW  PROFESSIONAL SURVEYOR  SURVEYOR	
Signed by Com C /Sil	クロー Date	November 19, 1997	
Burveyor's Michigan License No26	6453		