					Dec 20	1 100 6	)ii 100	+
SW cor., Sec. 9	LAND	CORNER RE	CORDATION	CERTIFICA	ATE	1 44 [	n -99	7.00
For corners in PAW PAW VAN BUREN	Filin I TWP.	g Requirement	t of Act 74, Mi	ch. P.A. 19 	70 May	1 44 F	114	۲.
(County)	Located In:	Corner Coo	le #			eren OF D		
1. Public Land Survey	T_3S. R_ TR TR	14W	E-5					04 10SUR
Property Controlling     in Section     Miscellaneous	TR_ S TR_ S TR_ S TR				IEC 2 8 199 SECTION			12/20 0104 10SURVEY
Property in Sec.	S TR_				Register	of Deeds St	amp & F	ile Nur <b>b</b> e
4. Lot No, Record 5. Private Claims, Record 5. Private Claims, Record 1. Allen H. McMachen, requirements of P.A. 74, Michigar conformance with regulations and united States Department of the inthat the corner points mentioned in that the corner points mentioned in the corner points	in a field survey on not not not not not not not not not	November 1,719 or points mentioned d in the current man anagement or by a d were in conformance	92to hereby sta in lines 1 and 2 a ual of survey instru tecree of a Court of a with the rules of the	bove were in uctions of the f Law and /or the Michigan	A B C  1 2 6 3 4 7 5 6 18	D E F G	10-15-15	J K L
Board of Land Surveyors or by recovered, found as expressed below		f Law; established,	re-established, n	nonumented,	8 19	20 21		_2324
NOTE: Not more than 2 come	ers, all in the same town	n and range, may t	be recorded		9			
on this certificate.					10 30 7	29 - 28	27-	-2625
					12 31 3	] 3233	34	_3536
A. Description of original mon	nument and accessorie	es and/or subsequ	uent restoration:		13	1   1		
1830 - William Brookfield, D 1950± - W.Q. Smith, C.S., Ar 1953± - T.A. Smith, R.L.S., A 1970± - D.R. Gilchrist, R.L.S. 1971± - A.H. McMachen, R.L. 1972 - A.H. McMachen, R.L. 1996 - D.R. Gilchrist, C.S., Fo Ave., 8' West of centerline of	ngle South to East is 88 ingle South to East is 8 , Found well point - 2 ingle Sound 11/4" pipe S., Found well point, 2 pund iron bar, cable ris 42 <sup>nd</sup> St	° 29' 30". 8° 28'. map witnesses go 4" Maple N. 5° W ser S. 40° W. 33.85'	ood, angle South 7. 90.5', 24" Mapl ', Cable riser S. 4	to East is 88° le N. 75° W. 8 5° E. 62.75′, 1	29′ 45″. 5.1′ .5′ South of cen		th	
B. Description of corner evidence	ence found and/or me	thod applied in re	storing or reesta	ablishing corn	er:			
Found iron rod per (2) 1996 iron rod was ratified by the						ience of corr	ner. Four	nđ
O Department of the control of		, , , , , , , , , , , , , , , , , , , ,	a najmahista ta	ating the sec-	ition of the white	OF M /	CH THE	
C. Description of monument for Location of found from is acc corner. Replaced from rod wi monument box over, Accessor	th a Standard Van Bui	ones established to lable evidence of t ren County Remoi	o perpetuate loc he position of th numentation Mo	ating the pos le original nument with	ition of the cor	ALLEN H. McMACHEN PROFESSIONAL		. washing
Nail & Tab in North side of 40" I Nail & Tab in East side of 30" Me Placed iron rod N. 22° W. 33.41' Placed iron rod N. 30° E. 46.76' Placed iron rod S. 40° E. 38.48' Placed iron rod S. 40° W. 24.32' 1.5' South of East and West road 8' West of North and South road	aple S. 10° W. 131.08′	accor Va	tatified by Peer Grance with P.A. 3 an Buren County Stranger	345 of 1998 Surveyor	LICENSES MANAGEMENT	SURVEYOR No. 16935 PROFES SIONA	SURVEY	THE STATE OF THE S
Signed by	HMIM	acken	J	Date	2/13	199		
Surveyor's Michigan License N	0	1693.	5	<del></del> -	6			

Lev 5 pg 304

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1985 REVISED OCT., 1995