MAY 1 5 1994

	COMMISSION 4 PALE 176
1BER	4 PALE 176

LAND CORNER RECORDATION CERTIFICATE OF 18 19 03 PM 194

Lero II Donie IDI	LAMB COMM	LITTIE GOTTE ATTOM GETT	11 OH 12 12	QU ,	4
LIBER 4 PAKE 176		ement of Act 74, Mich. P.			0
For corners in Paw Paw To	ownship		· Ma. 1.7	2 Smith	8
Van Buren County	Located In:	Corner Code ##	Ynauc	E SANCHA	را
(County)			กกัดใช้เรี	ลักร เรรียา	
1. Public Land Survey E¼ Post Sec 29	T 3S R14W	E-10			109JRVEY
	T R				E.
	T R				<u>50</u>
C. British Controlling	T R T R				
	T R				0101
	T R		Register of Deeds	s Stamp & File N	
	T R		negister of Deeds	- Stanip at he h	vanne Z
7 10porty in 5007					¥
4. Lot No, Recor	ded Plat		— АВС) E F G H I	η κ 22 ν
5. Private Claims					<u> </u>
				4-1-3-	
Donald R Gilchr	ist.	June 29, 1994	5 7 8	9-1-10-1	1112
I. Donald R. Gilchrist Survey on June 29, 1994, 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				16 15	1'41'3
current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				2122	2324-
Court of Law; established, re-established, monumented, re-monumented, recovered, found as					
expressed below:				28 27	2625
NOTE: Not more than 4 corne					
on this certificate.			12 - 31 - 35	23'33'4	3536
			ا ا امه		

A. Description of original monument and accessories and/or subsequent restoration:

Jan. 1830 - Government - William Brookfield, D.S., set post at 40 ch.; 10" poplar - N 6%° W - 17 lks.; 9" Poplar - S 86%° E - 10 lks. June 1873 - A.J. Teed, Co. Surveyor, found remains of old stake present, Book 4, P 125; put in new stake & stone on top; 9" B.Oak S 20° E 41 lks. 7/21/1891 - F.P. Lawton, Found stone, Book 5, P 47. April 1953 - W.Q. Smith, Co.Surveyor, shows Iron Pipe on drawing. August 1957 - W.Q. Smith, Co.Surveyor, R.R. spike; 40" Oak - S 29.6'; 12" Hick - N 31'; 48" Oak - SE 46.6'. March 2, 1970, Don Gilchrist, found R.R. spike - used in 8/77-7/76. June 28, 1972 -W.Q. Smith, Co.Surveyor, R.R. Spike (Rec'd Liber 1, P480). John Hunt,

found as Rec'd in 1975, 1986 & 1992.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Two wit's from (rec'd L-1, P480) remain Fd R.R. Spike 2" under new paving. & OK. Third wit's was cut down. Fd another R.R. spike down 6". Set a P.K. 1' S. Set a P.K. 1' W. Set a Harrison Marker. Corner approved at Peer Group Meeting on November 25, 1992. Recorded Liber 3, Pages 260 & 261.

Corner was field checked on 6/22/94 by D.R. Gilchrist, Co.Surveyor. Approved at the 6/29/94 Van Buren County Peer Group Meeting and is accepted as a careful and faithful perpetuation of the position of the Original Government Corner.

Ratified by Peer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position

Harrison Marker 50" W. Oak - South - 29.41' - Old Nail E side 32" Hick - North - 30.79' - use Old Nail in E side 24" W.Ch. - S 65° E - 82.02' Nail SW side CL of Rd.

Surveyor's Michigan License ND onald R. Gilchrist, RLS #13583

GILCHRIST SPORESSIONAL 1.13 (3533

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983