	DEC 20 1 44 PM •99
N ¹ / ₄ cor., Sec. 9 LAND CORNER RECORDA Filing Requirement of Act	ATION CERTIFICATE 74, Mich. P.A. 1970 Mark & Smile
For corners in PAW PAW TWP. VAN BUREN Located In: Corner Code #	RECUSTED CO D
(County)	REPORT OF THE PROPERTY OF THE
1. Public Land Survey	DEC 2 8 1999 87 87 88 88 88 88 88 88 88 88 88 88 88
2. Property Controlling in Section S TR	SECTION 3
3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L
5. Private Claims	2 6 5 4 3 - 2 - 1 -
	3
I, Allen H. McMachen , in a field survey on November 1719 99 99 h	pereby state that under 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines the conformance with regulations and rules therefore as required in the current manual of sur	rvey instructions of the fill
United States Department of the Interior, Bureau of Land Management or by a decree of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the	grues of the Michigan _
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, found as expressed below:	8 19 20 21 22 23 24
The state of the same and make may be reconstructed	ded 9
NOTE: Not more than 2 corners, all in the same town and range, may be reconnected on this certificate.	10 - 30 - 29 - 28 - 27 - 26 - 25
	11
	12 31 32 33 34 33 36
1830 – William Brookfield, D.S., Set quarter Section post, 8" Wh. Oak S. 75° W. 17 iks. (11.22') 1870 – A.J. Pierce, C.S., ½ post present – one witness tree remains and stump of other – But N. Hickory S. 42° E. 62 lks. (40.92') 1873 – A.J. Teed, C.S., "Found quarter post OK" 1923 – T.A. Smith, C.S., Found tin can with stone in it – drove ¾" pipe – put can over it and s 9" Walnut N. 51° 30' E. 47.0' to centerline/OK in 3/13/1962, 12" Walnut N. 27° 30' W. 48.3' to 1962 – W.Q. Smith, C.S., Found pipe, 18" Walnut S. 40° E. 60.9', P.Pole S. 30° W. 25.8' 1973 – W.Q. Smith, C.S., Found ¾" pipe with stones around, 16" Walnut N. 51° 30' E. 46.89, 1 Center line of 41" Street East 10', Center line of 52nd Avenue North 2' 1990 – D.R. Glichrist, C.S., Found ¾" pipe down 10" set 120D spike in top, Power pole S. 45° Stop sign N. 5° W. 41.45', 4' South of centerline 52nd Ave., 9' West of centerline 41" St.	stones around it. 18" Hickory S. 42° E. 41.3' to centerline/gone, o centerline/gone, Iron fence post S. 51° 30' E. 43.4'/gone 18" Walnut S. 35° E. 60.55', Street sign post N. 4° W. 21.62',
B. Description of corner evidence found and/or method applied in restoring	or reestablishing corner.
Found 120d nail in $\%''$ pipe per (3) 1990 witnesses. Top of pipe was 10" Location of pipe was ratified by the Van Buren County Remonumentation	below grade and surrounded by 3" – 8" diameter stones. ion Peer Group on April 28, 1999.
	WHAT I F M / DE TO THE TOTAL THE TOT
C. Description of monument for corner and accessories established to perp	etuate locating the position of the corner
Location of found ¾" pipe is accepted as a careful and faithful perpetuation original corner. Replaced found pipe with a Standard Van Buren County R Monument with monument box over, Accessories:	n of the position of the McMACHEN PROFESSIONAL
Post of stop sign N. 07° W. 43.54′ Placed iron rod North 31.99′ Van Bi	ed by Peer Group in No. 16935 Wren County Surveyor Professional Professional
Placed fron rod South 34.3' Placed iron rod S. 66° E. 59.80' 4' South of centerline road to East 9' West of centerline North and South road	20-99 D. R. S.
Signed by QOO HM Marks	
Surveyor's Michigan License No	