1993 LAND CORNER RECORDATION CERTIFICATE COMMISSION SEP 23 8 37 AH '93 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Lawrence Township Nack a Spills Van Buren County Located In: Corner Code ## 1. Public Land Survey Public Land Survey SE corner Section 33 T 3S R 15W G-13 T ____ R _ 2. Property Controlling __ T ____ R _ in Section \$ ____ R _ 3. Miscellaneous S ____ T ___ R __ Register of Deeds Stamp & File Number Property in Sec. ___ , Recorded Plat ___ 5 Private Claims Donald R. Gilchristn a field survey on _ July 26 , ₁₉ _93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: 4/1827 - Government Survey - William Brookfield, D.S. West on South boundary 80 ch. set Post Corner Witnesses: 50" cherry - N 60 Deg 20' E - 14 lks = 9.24' 32" beech - N 69 Deg 30' W - 24 lks. = 15.84' 12/1866 - C.J. Monroe, C.S.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Corners on South line of Section 34

Fd Stone & plump top set by W.H. GoSS SL Fd by Homer Ward, Co. Rd. Eng. Ward's witnesses ck. Approved on 7/28/93 by County Peer Group Meeting This corner is accepted as a careful & faithful perpetuation of the

original Section corner

(Continued on back of Certificate)

Measured 39.94 ch. (2636.04') & 39.94 ch. (2636.04') for Total of 5272.08'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Harrison Marker

Book 1

20" Hemlock - N 15 Deg W - 44.16 to Pk/W E. face

22" ash - N 60 Deg E - 56.96 to Pk/W S. face

P.P. - S 80 Deg W - 88.48 to Pk/W N. face

36" R.Oak - S 60 Deg 30' E - 95.47 to Pk/W S. face

Jog 104.4' E to NE corner Section 4 Hamilton Township 4' N of CL E&W Rd and on CL Rd N

Surveyor's Michigan License No. ___

3401 09/23 0104 10SURVEY

No. of Real Puny ESSION

DONALD R. **GILCHRIST** PROFESSIONAL SURVEYOR

Leller 4 Jane 42

A. Continued from front of Certificate ..

10/28/1868 - A. J. PIERCE, C.S.

Book 3

Found both witness trees.

Renewed witnesses and stake.

4/20/1871 Stake present, renewed, both withesses down, roots remain & agreed well.

Measured North 19.88 ch. (1312.08') to 1/8 Post & continued North 19.88 ch. (1312.08') to 1/4 Post for Total of 2624.16'.

1903 - J. S. HAINES, C.S.

Found a stone at 1/8 Post to North.

Measured North to 1/4 Post 19.95 ch. (1316.70').

No Date - W. H. GOSS, C.S.

Set Corner from Hamilton Corner.

Set Pump Top, Stake & Stone.

Witnesses: 13 "Walnut - S 33 Deg 15' E - 2.36 ch. = 155.76'.
21" Walnut - S 82 Deg 15' W - 3.305 ch. = 218.13'.

7/12/1934 - H. WARD, COUNTY ROAD COMMISSION.

Note.

Found Well Pump Casting surrounded with collar of stones. 4" below surface.

Witnesses: Corner of Stone foundation on House - N 41 Deg 15' W - 105.5' (see witness note).

10" Ash - N 60 Deg E - 58.0' to Center Line.
6" Walnut - N 75 Deg E - 108.0' to Center Line.
8" Ash - S 75 Deg 30' E - 127.7' to Center Line.
20" Red Oak - S 63 Deg 30' E - 94.7' to Center Line.

6" Walnut - S 47 Deg E - 123.6' to Center Line. Corner is 104.3' West of Hamilton Corner.

6/15/1992 - J. C. HUNT, P.S.

Recorded Survey (L9-P333)

Found Stone with "x" & small stones & irons around it.

In line with Center Line of Road North.

4' North of Center Line of Road E&W.

Set Iron with cap, South 33.0'.

Witnesses: 20" Pine - N 15 Deg W - 43.67'(nail in East face).

22" Walnut - N 60 Deg E - 57.37' (nail in South face).

Pole - S 80 Deg W.

East - 104.78' to 1/2" iron. NE Corner Section 4-4-15.

Letier 4 Jage 43