96-16601 D K7R4-13.tff

VAN BUREN COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DEC 17 2 24 PM 196

or	corners	in	Porter	Twp.

Van Buren	Located in:	Corner Code ##	SUNVEY MALL QUINCH		
 Public Land Survey Northeast Cor. Section 23 Property Controlling in Section Miscellaneous Property in Sec. 	T 4 S.R 13 W. T R R R R T R R R T R R R S T R R S T R R S T R R S T R R S T R R		MAY 1 6 1997 COMMISSION Register of Deeds Stamp & File Number		
John C. Hunt do hereby certify that under rein lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance wire Court of Law; established, in expressed below:	, in a field survey on Nov. 21 quirements of P.A. 74, Michigan P.A. of 1 n conformance with regulations and re uctions of the United States Departme a Court of Law and/or that the corner por th the rules of the Michigan Board of La re-established, monumented, re-mon	, 19 96 970, the corner points menti- ules therefore as required in ent of the Interior, Bureau of points mentioned in lines 3, 4 a and Surveyors or by a Decrea numented, recovered, foun	2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 12 13 14 13 14 13 14 13 14 13 14 13 15 14 13 15 14 13 15 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16		
A. Description of original	monument and accessories and/or - E.H. Lytle, D.S.	r subsequent restoration:	13		

North between sections 23 and 24 a distance of 80 chs. and set Post Corner. WITNESS:

22" Beech, S82°30'E, 1.25 chs. 11" Ash, N63°W, 23 lks.

Distance East is 80.03 chs.

Distance West is 39.51 chs.

(CONTINUED ON BACK OF CERTIFICATE)

Ratified by Peer Group in accordance with P.A. 345 of 1996
Van Buren County Surveyor

Date 12/17/96 D. R. S.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-7 Northeast Corner of section 23, T.4S.-R.13W., Porter Twp., Van Buren Co., MI. Corner common to sections 13, 14, 23 and 24.

No corner found, set by extending line through North quarter post and found 1/8 post between North quarter post and Northeast corner, measured West 1304.53' to found 1/8 post and continued West 1304.53 feet to North quarter post. Also measured East 2658' to centerline-centerline of C.R.352 & 23rd St. no corner found.

THIS GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS AT A MEETING HELD ON FEBRUARY 28, 1996, AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7 HARRISON MARKER IN MON BOX

S01°W, 57.10', set nail & washer in East face of pole.

NO2°W, 118.69', set nail & washer in East face of pole.

N57°W, 54.31', set nail & washer in Southeast root of 30" Maple.

S76°W, 79.05', set nail & washer in North face of 24" Maple.



9.00

•			•
Signed by John C. Hung A.5	. Б	ate December 15, 1996	
Surveyor's Michigan License No. 23513		TOTAL ADROGUED BY MISSINGAN CTAYE DEADD OF LAND CHEVEYOR	C 18M 30 407

Liber 4 Ag 452

3990 12/17 0104 10SURVEY

REVISED MAY 14, 1975 REVISED JAN., 1983 7/13/1905 - W.H. Goss, C.S.

Section 24

Set stones

Northeast corner to North quarter post = North quarter post to Northwest

Southwest corner to West quarter post = West quarter post to Northwest corner. Distance East is 20.12 chs. to eighth post, and continuing East 1327.92' to North quarter post.

Distance South is 40.165 chs to West quarter post, and continuing South 2650.89' to Southwest corner.

WITNESS:

36" Sugar Maple, S89°30'W, 67.5 lks.

18" Walnut, N26°W, 55.5 lks.

Found stone at North quarter post.

Found Stone over stake at West quarter post.

Eighth post on North line, West half is stone.

5/18/1916 - Section 23.

Measured West from Northeast corner 1304.16' and set stone Eighth post, continued West, 1304.16' to North quarter post (found pipe).

Distance South is 2650.89' to East quarter post.

A.bu. 4 Ag. 453