## JAN 1 7 1996 LAND CORNER RECORDATION CERTIFICATE

	COMMISSION Requirement	nt of Act 74, Mich. F	P.A. 1970
For corners In Van Buren	Located In:	Corner Code #	FILED
Porter Townshi	p S.E. corner Sec.	13	1
Public Land Survey	т <u>4 S <sub>R</sub> 13 W</u>	M-7	Dec 29 4 28 PH '95
,	T R	Eastern 117 .	DIN TA A SENTING
	T R T R		Mary On Could
2. Property Controlling			Y/(Well OMCY)
in Section	ST R		如此在對極主義的 (3) (3) (4)
3. Miscellaneous Property in Section	ST R ST R		Register of Deeds Stamp & File Number
roperty in deditori	<u> </u>		
	_ , Recorded Plat		A B C D E F G H I J K
5. Private Claims		Mar	2 - 6 5 4 - 3 2
			3
	May 10	0/	4 7 8 9 - 10 - 11 - 1
<ol> <li>Kobert E. Lemk do hereby certify that under</li> </ol>	(e, in a field survey on	, 19 <u>,</u> , 19 <u>,</u> 1970, the comer points me	ntioned 6 18 17 16 15 14
in lines 1 and 2 above were	e in conformance with regulations and rules t	herefore as required in the	current
Management or by a decre	tions of the United States Department of see of a Court of Law and/or that the corner p	points mentioned in lines 3	3, 4 and 8 20 20 21 22 23
5 above were in conforma	ance with the rules of the Michigan Board of established, re-established, monumented, re-	of Professional Surveyors e-monumented, recoverer	or by a 9
as expressed below:	established, to detablished, more memorited, in	5oa., . 00035. 42	10 -30 - 29 - 28 - 27 - 26 - 1
	corners, all in the same town and rang	je, may be recorded	11 12 31 32 33 34 35
on this certificat	ie.		13 32 33 34 35
, ,	inal monument and accessories and/or		
182/: United S Township		et post common t	o Section 13 & Section 24 on
Hickory	8" S. 54½° W. 33 T	inks	
Beech	22" N. 65 3/4° W. 34	4 links	
	tates Government Survey; 1: t town line 36 links North		ions 18 & 19, T. 4 S., R. 12 W.
Beech	24" N. 21° E. 38 1 ii		ost at intersection.
Beech	9" S. 72 <sup>0</sup> E. 19 li		
1905: Van Bure	n County Records Pg. 37; re	eads "Stone from	r Kalamazoo corner". 20" S. 51½º E. 86 links
B. Description of com	24" N. 44½° E. 89 1ii er evidence found and/or method app	lied in restoring or ree	stablishing corner:
			A drilled stone was found at the
Van Buren corn	er.	no discernible	markings were located at the
van baren corn	STE OF MON		
	Robert E.		
	Lemke Z	ľ	Ratified by Peer Group in 🔀 🚶
	LAND &		accordance with P.A. 345 of 1998
	SURVEYOR NO.		Van Buren County Surveyor
	One Land Survey	ŧ	1210 2-15-95 S. R.S.
	Land St	v	1916
	ument for corner and accessories esta		ified by the Van Buren County
			ound stones as detailed in Section
			eful and faithful perpetuation
	sition of the original corr in its place with a Monumer		one and placed 20" Harrison
	•	TO DOX OVER .	
	ne "W" Avenue North 21'	N 24 <sup>0</sup> 11	114 401
	e (@ ground) in Power Pole in E. side Power Pole	N. 34 <sup>0</sup> W. N. 24 <sup>0</sup> E.	114.40' 91.48'
PK Nail i	n W. side (2.5' above groun	nd) 18" Elm N	. 62 <sup>0</sup> E. 122.19'
PK Nail i	n N. side (3' above ground)	Power Pole S	. 80° E. 124.09'
Signed by Robe	I E Lemke	Date	12/28/95
Surveyor's Michigan Lic	ense No. 40160		APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
surveyor a milornyan Lic			REVISED MAY 14, 1975 REVISED JAN., 1983

7-00