SURVEY & REMONUMENTATION

JUN 1 4 1994

VAN BUREN COUNTY REMONUMENTATION PROGRAM

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			
Van Buren	Located In: Keeler Twp.	Corner Code ##	
1. Public Land Survey	Sec. 33, T4 S. R 16 W. S1 Post T R T R T R T R T R T R T R T R T R T	F-13	
2. Property Controlling	S T B		
in Section	S F		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
rioperty in Sec.	1 1		
	, Recorded Plat		— АВСDЕГGНІЈК L M
5. Private Claims			2 6 5 3 2 3
	_		4 7 8 9 4 10 4 11 12 12
do hereby certify that under in lines 1 and 2 above wer current manual of survey in Management or by a decree above were in conformance	• S • In a field survey on March requirements of P.A. 74, Michigan P.A. te in conformance with regulations an estructions of the United States Depart of a Court of Law and/or that the corner with the rules of the Michigan Board of the re-established, monumented, re-re-	of 1970, the corner points mentioned d rules therefore as required in the tment of the Interior. Bureau of Land er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a	8 19 20 21 22 23 24
expressed below:	, re-established, monumented, re-	nonamentos, resoveres, resire as	10 30 29 28 27 26 25
NOTE: Not more than	4 corners, all in the same town ar	nd range, may be recorded	11
on this certifica	ite.		12 31 32 33 34 35 36
A Description of origin	nal monument and accessories and	d/or subsequent restoration:	13
N46°30'W 53 1ks. Sec. 33-4-16) as P.O.I dist. from cor. bet. 1	34.98'. Jog 48.51' at ½ B. From lot cor. bet. Lots 70:	post. 1941 Plat of Krohne's $\& 71$ to $\frac{1}{4}$ post = 758.0'. 5/22 to the S_4 post of Sec. 33 as	N59°30'E 13 8.58', 5" White Oak is Peninsula 4-5-16 shows N _x post (S _x Post 2/1952 WQ Smith CS. His drawing shows 806.51', giving a jog of 48.51'. John 6" White Oak tree. Ratified by Peer Group in
			accordance with P.A. 345 of 1998
			Van Buren County Surveyor
B. Description of come	er evidence found and/or method :	applied in restoring or reestablis	hing corn bets 4/9/94200 Willia
Sla Post Sec. 33.	T4S-R16W, Keeler Twp.		· /
	oe 36' South of centerli	ine of road. Replaced w	with Harrison Marker & set survey
	RS, AND IS ACCEPTED AS A		BUREN COUNTY REMONUMENTATION PEER PERPETUATION OF THE POSITION OF
Re Ve	egister's Office Reco	red 4/11 1994 nack D. Smith	8.59 d'clock A M Cum Register
C. Description of monu	ment for corner and accessories of RKER	established to perpetuate locatin	ng the position of the corner:
	North 66.00', ½" I.I		
	0.7' South & 0.3' Ea S50°W, 25.70', NE co		end post for fence North & West.
	N80°E, 9.18', Set na	ail & tag in South face	
	S10°E, 5.91', Set na	ail & tag in NE face of	5" dia. Pine.
	r.l	BTR 4 - FACE 134	·/
7.0	ense No. 23513		13 4 4004
Signed by	c. Hunt, P.S.	Date <u>Apri</u>	LL 1, 1994
Surveyor's Michigan Lice	ense No23513	FORP	N APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
i		0823 04/11 010	04 10SURVEY 7-00 REVISED MAY 14, 1975 REVISED JAN., 1983