RC 1213

FEB 2 8 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

المالية والمراجع المراجع المرا			· · · · · · · · · · · · · · · · · · ·
For corners in	Filing Requir	rement of Act 74, Mich. P.	A. 1970
WAYNE	Located In:	Corner Code ##	უ ოფე ა
(County)			
Public Land Survey	T <u>1 \$ R 8 E</u> T R	К_3	La Carte
	T R		
2. Property Controlling	T R S T R		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
in Section	S T R		本党 る か
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		- Inegrater of Deeds Stamp & He Number
4. Lot No , R	recorded Plat		A B C D E F G H ! J K L M
5. Private Claims			
			2 - 6 - 5 - 4 - 5 - 2 - 1 - 1
			3 -
			4 - 7 - 8 - 9 - 10 - 11 - 12
i, PAUL V. SCHWIMMER, in a field survey on NOVEMBER 2, 19 93, 5			
do hereby certify that under red in lines 1 and 2 above were in			
current manual of survey instru			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			
expressed below:	e-established, monumented, re-	monumented, recovered, found	d as
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11
on this certificate.			12 31 32 33 34 35 36
			13
A. Description of original r	monument and accessories an	d/or subsequent restoration:	

NO G.L.O. WITNESSESS REMAIN, A POST WAS SET BY JOSEPH WAMPLER IN THE ORIGINAL SURVEY OF THE TOWNSHIP WHICH WAS COMPLETED MARCH 14, 1816.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: PREVICUSLY RECURDED IN:

WAYNE CO. RD. COMM 1970
FOUND CONC. MONUMENT IN MON. BOX (NO COVER)
NW 32.69' 12' MAPLE (GONE)
NE 39.54' D.E. POLE (MEAS 39.48')
SE 78.53' MBT POLE (GONE)
SW 49.14' MBT POLE (GONE)

49.14

1989 LIBER 24088, PG 804 FOUND IRON IN MONUMENT BOX

39.53′ 80.28′ 49.11′

N 40° E S 70° E

50*

NAIL E SIDE UTIL POLE (MEAS 39.48')
NAIL NE SIDE UTIL POLE (GONE)
NAIL N SIDE UTIL POLE (GONE)
SE CORNER BRICK HSE #41400 (MEAS 91.42')

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND CONC. MONUMENT IN MONUMENT BOX NEAR CENTERLINE OF SEVEN MILE ROAD N 05° E 47.81' SET NAIL & TAG WLY FACE 5" MAPLE N 35° E 39.48' SET NAIL & TAG ELY FACE P. POLE (PREVIOUS WITNESS) N 25° E 91.42' SE CORNER BRICK HSE #41400 (PREVIOUS WITNESS) SLY 20.04' SET NAIL & TAG 0.1' NORTH OF SLY EDGE OF PVMT S 30° E 128.88' SET NAIL & TAG NE FACE 12" DAK

NLY 60.12' FOUND 'T' IRON
DISTANCE TO L 3 MEASURED AS 2641.33' RECORDED IN 1930 AS 2641.43'
DISTANCE TO J 3 MEASURED AS 2641.03' RECORDED IN 1930 AS 2640.73'
SET REMONUMENTATION DISC AND CAP ON MONUMENT

THE SELECTED LOCATION IS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

Tau Signed by _

NOVEMBER 8, 1993 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

24618 Surveyor's Michigan License No.

⋾⋆

NOTE: NO BUREAU OF TAXATION 1930

WITNESSESS REMAIN (1930)