FER 28 1894

COMMEDICAL CAR

Surveyor's Michigan License No. 26467

## RC 1230 LAND CORNER RECORDATION CERTIFICATE Filing requirement of Act 74, Mich. P.A. 1970

Carry Michael Same				
For corners in WAYNE COUNTY	Located In:	Corner Code #	Compliance	with
(County)			ACT 345, P.A	1990
1. Public Land Survey	T 1S R 9E T R R	<u>K-7</u>	APPROVED ON: WAYNE COUNTY REMO	13/93 ACD ENÚMENTATION
2. Property Controlling S			Register of Deeds Stat	
in Section S			Register of Decomber	
Property in 222.	T R		ABCDEF	GHIJKLM
4 Let No B	ecorded Plat		1	
5. Private Claims			2 -6 -5 4	32-1
				<del></del>
COPERT I SMALLEY	in a field survey on NC	VEMBER 29 , 19 5	<b>33</b>	-10-11-12-5
do bereby certify that un	in a field survey on No. der requirements of P.A. 74, M a lines 1 and 2 above were in cor	lichigan P.A. of 1970	ations 5	1-1-1-1-1
corner points mentioned in	I lilites I ditto - total	curvey instructions (	stane 6 - 18-1-17-12	151413- h
and rules therefore as rec	delice in the content was b	Janagament of by a 0	lecree	
United States Department	Of the medical management	d in lines 3. 4 and 5	above - I do I do I di	222324
of a Court of Law and/or	that the cornerpoints mentioned the rules of the Michigan Board the costablished, monumented, it	d of Land Surveyors of	vered, 9	-+
Decree of a Court of Law	, le-earnmanach	G-Woundinguest	10 -3029 -28	3 -27 -2625
found as expressed belov	<b>V</b> :		11 1 1	11111
A A Second thora	corners, all in the same town a	nd range, may be rec	orded 12 -31323	3-34-357-367
NOTE: Not more than 4 on this certificat	te.		13	
				5 W
A. Description of origina	al monument and accessories an	d/or subsequent resto	ration:	1 N N N N N N N N N N N N N N N N N N N
GLO (1816): WPA (1930's): LCRC (1978): LCRC (1989): LCRC (1992):	"POST" "IRON NW-24" "1/2" IRON ROD ENCASED "FOUND 1/2" REROD IN M "FOUND 1/2" IRON ROD IN	IN CONCRETE IN I ONUMENT BOX" ( N MONUMENT BOX	MONUMENT BOX" (RC-57 RC-951; L. 24352, P. 717) " (RC-1043; L. 25755, P.	6; L. 20027(P=890) 660) 2 L 11 P
		d applied in restoring	or reestablishing corner:	m
B. Description of corn	er evidence found and/or metho	CUTOKED MUTNES	SSES RECORDED IN RC-104	13 AS FOLLOWS:
FOUND 1/2" IRO	N BAR IN MONUMENT BOX:	CHECKED WITH		M 94 19')
Az. 308°, 84.1° Az. 40°, 73.5° Az. 132°, 77.6 Az. 220°, 79.4	7'; CHISELED "X" IN S.E. 7'; CHISELED "X" IN S.W. 6'; CHISELED "X" IN N.W.	BOLT OF LIGHT PORT OF LIGHT I	OLE BASE. (MEAS. N 52° POLE BASE. (MEAS. N 40° POLE BASE. (MEAS. S 58° OLE BASE. (MEAS. S 40°	E, 73.53') E, 77.64')
C. Description of mo	nument for corner and accessor	ries to perpetuate loc	ating the position of the come	n:  MIDDLEBELT ROAD;
FOUND 1/2" IR	ON BAR IN MONUMENT BO)	( AT INTERSECTION ON" TAG AND SUR	VEY CAP NO. "30086-264	67" OVER IRON IN BOX
N. 52° W. 84.	10'. FOUND CHISELED ">	(" IN SOUTHEAST	BOLT OF CONCRETE LIGH	T POLE BASE.
N. 40° E. 73.	53'; FOUND CHISELED "	X" IN NORTHWEST	BOLT OF CONCRETE LIGH	T POLE BASE
S. 58° E. 77.	The state of the s	X" IN NORTHEAST	BOLT OF CONCRETE LIGH	I LOFE DWOF
S. 40° W. 79.			OR AND IS GENERALLY AC	CEPTED BY
PROFESSIONA	LOCATION IS ACCEPTED E L SURVEYORS AS THE BES	T AVAILABLE EVID		