APR 0.5 1996

LAND CORNER RECORDATION CERTIFICATE DEC 95 11:54 A.H. Filing Requirement of Act 74, Mich. P.A. 1979 REST E. YOUNGBLOOD, REGISTER

RECORDED

EDS

For corners	inCOMMISSION
Wayne	Chandle Colored A

Property in Sec.

Located In: Detroit Corner Code ## Public Land Survey 2. Property Controlling in Section Miscellaneous

LIBER 28471 PAGE Compliance with

WAYNE COUNTY, MI

APPROVED ON: 12-12-95 WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. _ , Recorded Plat _ 5. Private Claims __

William Roskelly ., in a field survey on . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

M-11) Northeast corner section 36, T.1 S., R.10 E., Redford Township

G.L.O. (1830's) Joseph Fletcher set corner post witnesses: Beech 10 N6 8 E9 (gone), Sug 9 S82 W20 (gone C. O. W.P.A. (1930's) No witnesses found.

No R.C.'s or C.S.'s found on file at Wayne County Register of Deeds.

WILLIAM ! ROSKELLY OYSYMUZ DI GOTERED LAND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-11) Northeast corner section 36, T.1 S., R.10 E., Redford Township

Found a monument box with an iron pipe in a concrete monument at the intersection of Plymouth and Greenfield Roads asphalt. This point is common to A-11 N.W. corner of section 31, T.1 S.,R.11 E.

Verified corner location by comparing City of Detroit data with field measurements:

M-11 to L-11 Record = 2606.91 Measured = 2606.53 M-11 to M-12 Record = 2628.90 Measured = 2629.14 Angle line M-11 & M-10 to M-11 & A-11 T.1 S., R.11 E. Record 89° 41' 33" Measured 89° 41' 19" Angle line M-11 & M-12 to M-11 & L-11 Record = 90° 32' 20" Measured = 90° 30' 05"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11) Northeast corner section 36, T.1 S., R.10 E., Redford Township

Found a monument box with an iron pipe in a concrete monument at the intersection of Plymouth and Greenfield Roads asphalt. This point is common to A-11 N.W. corner of section 31, T.1 S.,R.11 E.

The selected location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

WITNESSES:

Set nail and WCR tag N.W. face P. pole N. 65° E. Distance = 58.69

Set nail and WCR tag S.W. face P. pole S. 22° E. Distance = 71.17

Set nail and WCR tag N.W. face P. pole S. 47° W. Distance = 69.47

Set nail and WCR tag S.W. face Popole N. 44° W. Distance = 64.99

Placed Wayne County Remonuncentation brass marker and cap #10705

10705

Signed by Ulillia

Surveyor's Michigan License No.

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971