LAND CORNER RECORDATION CERTIFICATE 4.00 REMONIMENTATION Filing Requirement of Act 74. Mich. P.A. 1970 DEED Filing Requirement of Act 74, Mich. P.A. 1970 DEC 96 10:26 A.M. For corners in RECORDED FOREST E. YOUNGBLOOD, REGISTER EDS WAYNE Corner Code # Located In: WAYNE COUNTY, HI CITY OF DETROIT T 1S R 11E 1. Public Land Survey Compliance with ACT 345, P.A. 1990 APPROVED ON: DEC. 6 2. Property Controlling WAYNE COUNTY REMONUMENTATION in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. G н \_, Recorded Plat 4. Lot No. 5. Private Claims OCTOBER 10, 96 \_, in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in 7 lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current 8 manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 11 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: UNDER CONTRACT FOR THE GLO ORIGINAL SURVEY (DATED SEPT., 1816), JOSEPH FLETCHER SET A POST. NO EVIDENCE OF ORIGINAL CORNER FOUND. L. 34 P. 25 **BIRWOOD PARK GLENDALE COURTS SUBDIVISION** 8-16-1916 L. 35 P. 24 L. 39 P. 96 **B.E. TAYLOR DETROIT CITY SUB'N No.1** JOHN M. WELCH JR'S WYOMING-SCHOOLCRAFT SUBDIVISION 9-27-1923 L. 46 P. 98 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: RE-ESTABLISHED CORNER ALONG THE CENTERLINE OF WYOMING (66' WD.(ASPHALT)) USING FOUND PROPERTY CORNERS ALONG THE WEST LINE OF WYOMING AND WALK AND STREET SPLITS OF WYOMING WITH REFERENCE TO GLENDALE COURTS SUBDIVISION. VERIFIED LOCATION WITH OTHER FOUND PROPERTY CORNERS ALONG WYOMING AND USING WALK AND STREET SPLITS WITH SHIP STATE OF MICHO REFERENCE TO THE ABOVE LISTED PLATS. PROFESSIONA O SURVEYOR O SURVEYOR O No. 30081 STATES OF SESSIONA SURVEYOR OF SESSIONA SURVEYO DUNN C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E-9 SOUTHWEST CORNER SECTION 21 T.1S., R.11E. PLACED BRASS WAYNE COUNTY REMONUMENTATION WASHER AND PLASTIC CAP #30081 ON 1/2" x 18" IRON REBAR WITHIN A NEW MONUMENT BOX. WITNESSES SET P.K. NAIL WITH WAYNE COUNTY REMON TAG IN WEST FACE OF UTILITY POLE N.17°E 105.51 SET P.K. NAIL WITH WAYNE COUNTY REMON TAG IN CONCRETE WALK S.71°E. 41.26 "X" IN STONE CURB S.35°W. 41.45 SET P.K. NAIL WITH WAYNE COUNTY REMON TAG IN CONCRETE WALK 35.19 N.55°W. THE SELECTED LOCATION IS A CAREFUL AND FAITHFUL RE-ESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

30081

Surveyor's Michigan License No.