SURVEY & REMONUMENTATION

Surveyor's Michigan License No.

FILE DOAND TOWN LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTIO	N	Liber-	-29744 Page-1025.0
WAYNE		lo mer Code# 973353 STHER	-29744 Page-1025.0 332LS 12/22/1997 10:11AM
(County)	COT OF HAMINAMOR	THER	
1. Public Land Survey	TISRILE		
	T R		
	T R #	008	
2. Property Controlling	STR		Compliance with
in Section	S TR		ACT 345, P.A. 1990
3. Miscellaneous Property in Sec.	S T R		APPROVED ON: 12-2-97
Troperty in occ.	·		WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No. Reco	orded Plat		Register of Deeds Stating & File Number
	T CORNER OF 1/4 SECTION 16, T.T.	A.T.	ABCDEFGHILKIM
I, STEVEN E. DUNN, in a field survey on NOVEMBER 25, 1997,			
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules			3
therefore as required in the cur	rent manual of survey instructions of the United S	States	4 7 8 9 10 11 - 12
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as			5
			618 17 16 15 14 13 7
expressed below:	mainemen, re-monunicinea, recovered, round i		8 19 20 21 22 23
NOTE: Not more than '	2 corners, all in the same town and ra	nga may ba	9 9 20 21 22 23
recorded on thi		nge, may be	10 . 30
			11
A. Description of original i	nonument and accessories and/or subsequen	t restoration:	12 31 32 33 34 35 36 13
TEN THOUSAND ACRE TRA	CTS SURVEY BY JOSEPH FLETCHER IN 1	816, SET A POST	Consider to Face to a forest from Proper resistance of a
NO EVIDENCE OF ORIGINAL	L CORNER		
PLATS			AMILIAN,
L. 10 P. 18	"HIGHLAND PARK SUB'N"	11-11-1886	MICA/OF MICA/
L. 21 P. 96 L.24 P. 76	"GOODRICH & BURTONS ALLOTMENT "SUB'N OF BLKS 1,2,3,4,7 & 10	i" 9-7-1900 5-10-1906	STEVEN E
			DUNN *
			SURVEYOR S
			28408
			POFESSIONAL
B. Description of corner evi	idence found and/or method applied in resto	ring or reestablishing corr	ner:
NO EVIDENCE OF EXISTING	CORNER		
RE-ESTABLISHED CORNER	USING CITY OF DETROIT CONTROL DRA	WINGS AND STONE CUF	RB AND WALK SPLITS.
HELD DETROIT CONTROL F	DRAWING TO ESTABLISH NORTH-SOUTH	I INF	42 AA DECA
			\$7.00 DEED RECORDED
HELD RECORD OFFSET DISTANCE AND STREET SPLITS TO ESTABLISH EAST-WEST LINE			FOREST E. YOUNGBLOOD, REGISTER OF SE WAYNE COUNTY, HI
	•		Receirt #43579
C. Description of monument SE CORNER OF 1/4 SEC. 16	for corner and accessories established to per (T.T.A.T.), T.1S.,R.11E., (PRORAT	petuate locating the position	on of the corner:
PLACED ALUMINUM WAYNE	E COUNTY REMONUMENTATION CAP w/#	∵ 28408 ONCONCRETE M	ONUMENT WITH 1/2" REBAR IN NEW MONUMENT BOX.
WITNESSES			•
15°AZ. 30.80' \$	SCRIBED "X" IN TOP OF SOUTHWEST BOIL		\$4.00 REMONUMENTATION
	SCRIBED "X" IN CONC. CURB AT SOUTH I OUTSIDE CORNER OF BRICK WALL.	END OF CURB RETURN.	,
	NSIDE CORNER OF BRICK WALL.		
	•	•	
THE SELECTED LOCATION	IS A CAREFUL AND FAITHFUL RE-ESTAB	LISHMENT OF THE DOS!	TION OF THE ORIGINAL CORNER
THE SELECTED LOCATION	TO A CANEL OF AND FAITHFUL RE-ESTAD	LOTHERY OF THE POST	
			•

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983

1997