3

6

10

11 12

ı	# I	V	U	•	AP	R	U	5	19 98 ND	CORNER	REC	Q
									Filing	Requirem	ent d	'n

RDATION CERTIFICATE of Act 74, Mich. P.A. 1970 HAR 96 10:24 A.H.

For	co	rne	rs	in
vi	vv	1116	13	1113

WAYNE

COMMISSION

Located In: Corner Code # HAMTRAMCK TWP (NOW CITY OF DETROIT)

1. Public Land Survey

(County)

Т 2. Property Controlling in Section Т

, Recorded Plat

3. Miscellaneous Property in Sec.

R R Ŧ

R -11E 12E

\$ 4.00 REMONUMENTATION Compliance with ACT 345, P.A. 1990

APPROVED ON: DEC WAYNE COUNTY REMONUMENTATION PEER GROWN TOWNTTEE

RECORDED

FOREST E. YOUNGBLOOD, REGISTER OF DEEDS

WAYNE COUNTY, MI

Register of Deeds Stamp & File Number

5. Private Claims

Note: This Certificate is being re-recorded to correct a typographical error in the range number

MARTIN C. DUNN in a field survey on OCTOBER 29, 19 95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established. re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND

GLO ORIGINAL SURVEY PERFORMED BY JOSEPH FLETCHER UNDER CONTRACT DATED SEPT., 1816

PLATS

L. 22 P. 39

J.W. NUERENBERG'S SUBDIVISION TUMEY'S SUBDIVISION

JULY 18, 1901 APRIL 25, 1911 MARTIN C.
DUNN
PROFESSIONAL
SURVEYOR
No.
30081

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NO EVIDENCE OF CORNER FOUND.

HELD FOUND IRON PIPES ON WEST SIDE OF VAN DYKE. EXTENDED LINE RECORD DISTANCE TO ESTABLISHED CORNER.

VERIFIED LOCATION USING CURB SPLITS.

PLACED WAYNE COUNTY REMONUMENTATION MARKER AND ALIMINIUM CAP #36081 ON 1/2" x 18" IRON WITHIN A MONUMENT BOX.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 T.1S., R.12E. WAYNE COUNTY REMONUMENTATION MARKER AND ALUMINUM CAP #30081 ON 1/2" x 18" ROD IN MONUMENT BOX.

Date

WITNESSES

SET PK NAIL WITH W.C.R. TAG IN CONC. WALK 0.50' SOUTHWEST OF FACE OF SIGNAL POLE AZ. 33º 71.25

SET PK NAIL WITH W.C.R. TAG IN CONC. WALK 2.00' EAST OF CENTERLINE OF HYDRANT

60.67 SET PK NAIL WITH W.C.R. TAG IN CONC. WALK 3.20' SOUTHEAST OF FACE OF SIGNAL POLE AZ. 233°

SET PK NAIL WITH W.C.R. TAG IN CONC. WALK EXPANSION JOINT A7, 310° 62.10

THE SELECTED LOCATION IS FOR THIS PROPERTY CONTROLLING MONUMENT IS ACCEPTED AS A CAREFUL AND FAITHFUL DETERMINATION OF THE POSITION INDICATED.

DECEMBER 5, 1995

30081 Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN. 1983

12

13

C

0

7