SURVEY & REMONUMENTATION

APR 2 5 1995

RC 1498

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in	Filing Require	ement of Act 74, Mich. F	P.A. 1970		
WA'	YNE	Located In:	Corner Code ≠≠	: LI27797PA644		
	(County)	TOWNSHIP OF CANTON	Joine, Jode 44	~ * * O \$ I VO 4 4		
1.	Public Land Survey	T <u>2S</u> <u>R8E</u> T <u> </u>	L-13	Compliance with ACT 345, P.A. 1990 APPROVED ON: 12-7-94	ı	
2.	Property Controlling in Section	T R S T R S T R		WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE	N C	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number		
4.	Lot No , Re	corded Plat		Q	Ď	
5.	Private Claims			A B C D E F G H 1 J K L		
do h in h cum Mar abo Cou exp.	nereby certify that under requines 1 and 2 above were in order than and 2 above were in order than and of survey instructing ement or by a decree of a love were in conformance with into flaw; established, revessed below:	in a field survey on NOVEM irrements of P.A. 74, Michigan P.A. oconformance with regulations and tions of the United States Departm Court of Law and/or that the corner the rules of the Michigan Board of established, monumented, re-moners, all in the same town and	f 1970, the corner points menti- rules therefore as required in nent of the Interior, Bureau of points mentioned in lines 3, 4 a Land Surveyors or by a Decre- onumented, recovered, foun	tioned in the fLand and 5 and 5 and as 10 30 29 28 27 26 2	24-	
A.	ORIGINAL GOVERNMENT SI G.L.O. (1816) DESCRIP WITNESSES: ASH 24: SUGAR 12:	onument and accessories and/ URYEY BY T. WAMPLER, D.S. (TION OF CORNER NOT STATED I S 57 W 28 (18.48 R)(GONE) N 9 E 27 (17.82 R)(GONE) TION OF ALBERT E. CHAMPNEY,	1815-1819) N NOTES			
	(CONTINUED ON BACK)					
3.	DISTANCE TO K-13 MEASU DISTANCE TO M-13 MEASU L.18746 P.842 FOUND 1,	dence found and/or method apoument Box in Centerline of JRED AS 2656.19'; RECORD WP/JRED AS 2638.78'; RECORD WP/2" ROD IN MONUMENT BOX (19) FILITY POLE (MEASURED 41.16) FILITY POLE (GONE)	A (1930) DISTANCE OF 26: A (1930) DISTANCE OF 26: 74)	555.61		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13 SOUTH 1/4 CORNER SECTION 36 T.2S, R.8E FOUND 1/2" ROD IN MONUMENT BOX IN CENTERLINE ASPHALT ROAD AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

WITNESSES: N 40° E 75.39 CENTERLINE TOP OF HYDRANT

N 45° E 43.15 GAS MARKER (GONE) S 50° E 50.21 30" ELM (GONE)

N 48° E 71.48 NAIL IN CAP SOUTHEAST SIDE 16" TREE

S 45° W 44.80 NAIL IN CAP CENTERLINE TOP GUARDRAIL POST

S 85° W 35.18 IRON IN MONUMENT BOX (PREVIOUSLY USED)

N 45° W 41.16 FLASH IN EAST SIDE UTILITY POLE

\$ 16.00 MISCELLANEOUS RECORDING 27 DEC 94 11:02 A.H. RECEIPT# 48A RECORDED

FOREST E. YOUNGBLOOD, REGISTER OF DILLOS WAYNE COUNTY, HI

O'ROURKE

PROFESSIONAL SURVEYOR No. 16937

PLACED REMONUMENTATION BRASS AG AND CAP #16937 ON RE-ROD

Date

12-27-94

Signed by Surveyor's Michigan Licenson NE

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 24, 1911 REVISED MAY 14, 1915 REVISED JAN . 1983

LI27797PA645

SECTION A (CONTINUED)

W.P.A. (1930s) CROSS S 36 #158

WITNESSES: NE 43.53 CONCRETE ROAD SIGN POST (GONE)

SE 50.40 26" ELM (GONE)

SW 60.13 POLE (GONE)

W 35.18 IRON (MEASURED 35.18)

NW 42.16 EDISON POLE (MEASURED 41.82)

W.C.R.C. (1970s) MONUMENT IN BOX S 36 #158

WITNESSES: NE 42.98 SOUTHWEST CORNER ROAD SIGN BASE (GONE)

SW 62.85 DETROIT EDISON POLE (GONE)

SW 59.88 MICHIGAN BELL TELEPHONE POLE (GONE)

W 35.18 IRON (MEASURED 35.18)

NW 41.80 DETROIT EDISON (MEASURED 41.82)