## RC 1501

## LAND CORNER RECORDATION CERTIFICATE

L127797PA650

T(

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code ## (County) TOWNSHIP OF CANTON CDMMDN1 Compliance with T 25 R8E 1. Public Land Survey ACT 345, P.A. 1990  $\Pi$ \_ R. T 25 R 9 E APPROVED ON: <u>12-</u>7-9 T \_\_\_\_\_ R \_\_ WAYNE COUNTY REMONUMENTATION \_\_ R PEER GROUP COMMITTEE \_ T \_\_ 2. Property Controlling \_\_ T \_\_\_\_\_ R . in Section \_\_ T .\_\_\_ R . Miscellaneous Register of Deeds Stamp & File Number Property in Sec. ... T ... \_ , Recorded Plat \_ Private Claims \_ 18 . 19 *74* I. E. PATRICK O'ROURKE... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: \$ 16.00 MISCELLANEOUS RECORDING ORIGINAL GOVERNMENT SURVEY BY T. WAMPLER, D.S. (1815-1819) RECEIPT# 48A 27 DEC 94 11:03 A.M. G.L.O. (1816) DESCRIPTION OF CORNER NOT STATED IN NOTES RECORDED WITNESSES: ASH 16 EAST 11 (7.26' R) (GONE) FOREST E. YOUNGBLOOD, REGISTER OF DEEDS IRONWOOD 4 S 63 W 4 (2.64' R) (GONE) RESURVEY AT THE DIRECTION OF ALBERT E. CHAMPNEY, DIRECTOR OF WAYNE COUNTY BUREAU OF TAXANGUN COUNTY, HI (CONTINUED ON BACK)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DISTANCE TO M-3 TRAVERSED AS 2641.98'; RECORD WPA (1930s) DISTANCE OF 2642.58' DISTANCE TO M-5 TRAVERSED AS 2634.17'; RECORD WPA (1930s) DISTANCE OF 2634.02' L.C.R.C. #365 L.18960 P.699 FOUND 1" IRON PIPE

NORTH 9.88' FENCE POST (GONE)

SOUTH 3.45' FENCE POST (GONE)

N 40°W 40.00' CORNER OF BLOCK BARN (GONE)

N 10°W 36.90' CORNER OF BARN (GONE)

NO OTHER L.C.R.C. ON RECORD AT WAYNE COUNTY REGISTER OF DEEDS



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

EAST 1/4 CORNER SECTION 12 T.2S, R.8E

FOUND 3/8" RE ROD ON WOOD FENCE LINE, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER

WITNESSES: N 2°30' E 67.83' CENTERLINE TOP OF FIRE HYDRANT

N 88°30'E 67.72' NORTHWEST CORNER METAL BASE ON TOP OF CONCRETE BASE OF LIGHT POLE

S 89°30'E 40.95' SOUTHWEST CORNER CATCH BASIN RIM

S 1°30' E 78.82' NAIL/FLASHER EAST SIDE UTILITY POLE

PLACED A REMONUMENTATION BRASS TAG AND CAP #16937 ON RE-ROD.

Signed by

E. PATRICK O'ROURKE
Surveyor's Michigan License No. 6937

12-27-94

2 K 14 D

## SECTION A (CONTINUED)

WPA (1930s) SET IRON E-12 #52

WITNESSES: NORTH 99.35' 14" CHERRY (GONE)

SW 75.00' 30" ELM STUMP (GONE)

· 100 · 100

WEST 39.12' 6" MAPLE (GONE)

102.08' 12" TWIN ELM (GONE)