APR 2 5 1995

COMMISSION

Lot No. _____, Recorded Plat

5. Private Claims _

LAND CORNER RECORDATION CERTIFICATE 13.00 MISCELLANEOUS RECORDING
RECORDATION CERTIFICATE 13.00 MISCELLANEOUS RECORD

Filing Requirement of Act 74, Mich. P.A. 1970 in Caule For corners in FOREST E. MALGOS JULY, REGISTER OF DEEDS WAYNE Corner Code =## LA S GERTY, M. Located In: (County) Compliance with C-5 T 25 R 9E 1. Public Land Survey -ACT 345, P.A. 1990 R APPROVED ON: _11-21-94 MICHIQ ___ R _ WAYNE COUNTY REMONUMENTATION __ R т PEER GROUP COMMITTEE R 2. Property Controlling Т in Section . T. PALCZYNSKI _ R Т Miscellaneous Register of Deeds Stamp & File Number PROFESSIONAL Property in Sec. VEYOR No.

OFE 88101

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL G.L.O. SURVEYOR: FLETCHER MAY 27,1817

NANKIN TOWNSHIP

DESCRIPTION OF POST SET FOR CORNER MONUMENT NOT STATED IN FIELD NOTES.

DESCRIPTION OF POST SET FOR CORRER MONUMENT NOT STRIED IN FIELD NOTES.

WITNESSES LISTED: W.O. 12 S 89 W 34 (22.4') (GONE) & DO. "20 S 43 E 39 (25.7') (GONE)

W.P.A.-(1930'S) NW-17 IRON. WITNESSES SHOWN: TEL. POLE NE 42.7' (GONE)

POLE SE 48.53'(GONE)
ROAD SIGN SW 42.38'(GONE)

10

11

12

13

R.C.#491,L.19486,P.378-379 VENT PIPE NW 63.9! (GONE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" IRON IN MON BOX AT FORD RD / NEWBURGH RD. (ASPHALT PAVEMENT)

MEASURED DISTANCES FOR COMPARISON TO W.P.A. RECORDS:

C-5/C-4:WPA=2619.31'; MEAS=2619.30'; C-5/B-5:WPA=2609.88'; MEAS=2610.18'

B-5/C-5/C-4: WPA=90°11'50"; MEAS=90°11'38"; C-5/D-5:WPA=2630.49; MEAS=2630.40'

C-4/C-5/D-5: WPA=89°43'45"; MEAS=89°43'03"

R.C.#491 L19486, P378-379(8-13-76) WCRC SEC COR WITNESS RECORD (2-13-70) IRON IN BOX 5/8" IRON PIPE IN HAND HOLE. 72.97' (GONE) N45°E 72.95'(GONE) ED POLE NE NAIL NW SIDE L.P. NAIL SW SIDE L.P. \$45°E 63.67'(GONE) ED POLE SE 63.69' (GONE) SW 50.20' (GONE) NAIL NW SIDE L.P. S25°W 50.21'(GONE) MBT POLE 62.75' (GONE) PK NAIL E SIDE L.P N45°W 49.18'(GONE) BLOCK BLDG NW

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5:SECTION CORNER 7,8,17&18, T2S R9E, FD 3/4" IRON/MON BOX IN NEWBURGH/FORD.THE

SELECTED LOCATION IS ACCEPTED BY THE CONTRACTOR AND IS GENERALLY ACCEPTED BY

PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE

ORIGINAL CORNER. PLACED W.C.REMON. BRASS MARKER AND CAP "PPP PS 30096".

SET NAIL/WCR TAG IN SOUTHEAST FACE UTILITY POLE

N35°E 86.33'

SET NAIL/WCR TAG IN SOUTHEAST FACE UTILITY POLE	N35°E	86.33'
CENTERLINE WCRC BENCHMARK BRASS DISC#70-80.	N45°E	80.56'
FOUND "X" IN NORTHWEST BOLT TRAFFIC CONTROL POLE.	s45°E	82.35'
SET NAIL/WCR TAG IN NORTHWEST FACE UTILITY POLE.	s20°W	84.29'
CENTERLINE OF FIRE HYDRANT STEM.	s50°W	78.68'
SET NAIL/WCR TAG IN NORTHEAST FACE OF UTILITY POLE.	n35°W	77.72'

Signed by PYPSIC Date 22.DEC94

Surveyor's Michigan License No. 30096

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

RC 1455

11 0 - MISC