22 DEC 94 12:01 P.M. RECEIPT# 35B

APR 2 5 1995

		COMMISSION
For	corners	

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ETROGR<mark>ed</mark> Etrogresister of deeds

WAYNE Located In: Corner Code ## (County) T_25 R C-13 1. Public Land Survey . _....R OF MICHIG R _ R . _ R 2. Property Controlling PETER F in Section Т _ R Palczynski _ R 3. Miscellaneous PROFESSIONAL Property in Sec. R SURVEYOR No., Recorded Plat 30098 5. Private Claims _ OFE \$510

Compliance with ACT 345, P.A. 1990

APPROVED ON: 11-21-94 WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

P.P. Palczynski 7 November , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

ORIGINAL G.L.O. SURVEYOR: FLETCHER MAY 27, 1817.

DESCRIPTION OF POST SET FOR CORNER MONUMENT NOT STATED IN FIELD NOTES.

WITNESSES LISTED: W.O. 20 N51E 23 (15.2') (GONE) & B.O.24 S84E 98(64.7')(GONE)

GLO NOTES-T3S, R9E: "FELL 1.79 (118.14') W OF POST COR 31,32 T2S, R9E"

W.P.A.-(1930'S) SW-32 IRON. WITNESSES SHOWN: ED POLE

IRON

63.74'(GONE)

NANKIN TOWNSHIP

15" MAPLE 83.62' (GONE) SE

15" MAPLE

SE

9

10

12

69.17'(GONE)

115.64' (MEAS=115.87')

ROOT 30" MAPLE S 25.47' (GONE)

C.S.#1120 L.19125, P.305-306 (5-17-75)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" STEEL BAR IN CONC MON/MON BOX IN VAN BORN ROAD. (ASPHALT PVT.) MEASURED DISTANCES FOR COMPARISON TO W.P.A. RECORDS:

C-13/D-13 W.P.A. = 2611.69

MEAS. = 2611.54'

C-13/B-13 W.P.A. = 2631.32'

MEAS. = 2631.79'

B-13/C-13/D-13 W.P.A. = 180° 01' 15"

MEAS. = 180° 02' 10"

C.S.# 1120, L19125, P305-306 (5-17-75)

NAIL WITH SQUARE TAB IN D.E. POLE

NE

56.11'(MEAS=56.02')

NAIL WITH SQUARE TAB IN MBT. POLE

SE

57.85' (GONE)

MONUMENT IN ROAD BOX

WEST

_ Date

115.82'(MEAS=115.87')

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-13: SECTION CORNER 31&32 T2S R9E, FOUND 1/2" IRON BAR IN CONC MON/MON BOX. THE SELECTED LOCATION IS ACCEPTED BY THE CONTRACTOR AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. PLACED W.C.REMON. BRASS MARKER AND CAP "PPP PS 30096".

SET NAIL/WCR TAG IN SOUTHEAST FACE OF 15" BEECH. SET NAIL/WCR TAG IN SOUTHEAST FACE OF UTILITY POLE. SET NAIL/WCR TAG IN NORTHEAST FACE OF UTILITY POLE. SET NAIL/WCR TAG IN NORTHWEST FACE OF UTILITY POLE.

N36°E 58.88' N54°E 56.31' S54°E 56.22'

99.37

87.471 115.87

FOUND 1/2" STEEL BAR IN BROKEN MON/MON BOX. SET NAIL/WCR TAG IN SOUTH FACE OF UTILITY POLE.

N70°W

22 DEC

S68°W

WEST

Surveyor's Michigan License No. _____

Signed by .

30096

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975**

11. D-MUSC