APR 2 5 1995

\$ 13.00 MISCELLANEOUS RECORDING 22 DEC 94 12:05 P.N. RECEIPT# 35B

RECORDED

CON	a a	835	 	A.
1. 18 Cart 1	1	168.	 . 5	- 1

LAND CORNER RECORDATION CERTIFICATEOREST E. YOUNGBLOOD, REGISTER OF DEEDS MAYNE COUNTY, MI Filing Requirement of Act 74 Mich D. 8 4070

For corners in	rining nequi	ement of ACL 14, MICH. P	'.A. 1970	HILLIAM CHUILLY 114	
WAYNE	Located In:	Corner Code ##			
(County)		Conici Code	•		1
Public Land Survey .	T R	M-5 OF MICHIGA	AC	Compliance with 17 345, P.A. 1990 ON:	Od.
2. Property Controlling in Section	S T R	PETER P. PALCZYNSKI	WAYNE COU	NTY REMONUMENTA GROUP COMMITTEE	TION
Miscellaneous Property in Sec. .	S T R F S T R F	PROFESSIONAL C SURVEYOR O	Register of De	eeds Stamp & File N	umber
4. Lot No, 1	Recorded Plat	30096 SE			
5. Private Claims	<u> </u>	A	A B (CDEFGHI	JKLW
	•	No. 30096	2 6 -	_543	
do hereby certify that under re in lines 1 and 2 above were l		November 94 of 1970, the corner points mention rules therefore as required in	oned 6 18	-17-1615	-11 -12
Management or by a decree of above were in conformance wi	a Court of Law and/or that the corne ith the rules of the Michigan Board or re-established, monumented, re-	er points mentioned in lines 3, 4 a of Land Surveyors or by a Decree	and 5 8 19	-20 -21 -22	2324
NOTE: Not more than 4 con this certificate.	corners, all in the same town ar	nd range, may be recorded	11 12 -31	32 33 34	35-36-
	monument and accessories and consumer and co			ANKIN TOWNSHIP	
DESCRIPTION OF	F POST SET FOR CORNER	MONUMENT: NOT STATED	O IN FIELD NOT	ES.	7 7

WITNESSES: ELM 20 N 86 W, 33(21.8)(GONE) & LYNN 9 S 53 E, 13(8.6)(GONE)

G.L.O. NOTES - T2S, R10E: "COR SEC 12, 13 T2S, R9E" (NO FALLING NOTED)

W.P.A.-(1930'S)NE-13 IRON, WITNESSES SHOWN: TEL POLE SE 52.47' (GONE)

ROAD MRKR NW 47.23'(GONE)

BASE FIRE HYD SW 77.5' (MEAS=77.68')

W.P.A.-(1930'S) NW-18, T2S, R10E, SAME WITNESSES TO IRON, AS SHOWN ABOVE.

C.S.#134, L18022, P53; C.S.#135, L18022, P54; R.C.#45, L18022, P7.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BRASS CAP "MDSHT RLS 13589 ON CONCRETE MONUMENT IN MONUMENT BOX. (CONC. PVT) AT INKSTER ROAD AND FORD ROAD INTERSECTION.

MEASURED DISTANCES FOR COMPARISON TO W.P.A. RECORDS:

M-5/M-4:W.P.A. = 2566.52' MEAS=2566.58' M-5/M-6:W.P.A.=2640.14' MEAS=2640.31'

M-5/L-5:W.P.A. = 2660.17' MEAS=2660.49' M-5/B-5:W.P.A.=2636.36' MEAS=2636.22'

M-4/M-5/B-5:WPA=90°29'00" MEAS=90°29'11" B-5/M-5/M-6:WPA=89°33'00"MEAS=89°33'19"

M-6/M-5/L-5:WPA=89°31'10" MEAS=89°30'51" L-5/M-5/M-4:WPA=90°26'45"MEAS=90°26'30"

R.C.#45 L18022, P7, (3-22-72) FOUND IRON BAR IN MONUMENT BOX.

M.S.H.D. NAIL IN EDISON POLE N41°W 59.60' (GONE)

W.C.R.C. NAIL IN EDISON POLE \$53°E 64.05' (GONE)

M.S.H.D. NAIL IN EDISON POLE \$44°W 74.15' (GONE)

SET NAIL/WCR TAG IN SOUTHWEST FACE OF UTILITY POLE.

30096

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-5:SECTION CORNER 12 & 13 T2S R9E FOUND BRASS CAP ON CONCRETE MON IN MON BOX.THE SELECTED LOCATION IS ACCEPTED BY THE CONTRACTOR AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. NO W.C.REMON. BRASS MARKER OR CAP "PPP PS 30096" PLACED. ٥E 158.69

SET NAIL/WCR TAG IN	SOUTHEAST FACE OF UTILITY POLE.	N10°E
SOUTHWEST CORNER OF	BUILDING #27350.	N45°E
FOUND NAIL/MDSH TAG	IN NORTHEAST FACE OF UTILITY POLE.	S53°E
FOUND NAIL/MDSH TAG	IN SOUTHEAST FACE OF UTILITY POLE.	s40°W
CENTERLINE OF BRASS	DISC WCRC BENCHMARK #120-80.	s45°W

S45°W 80.95

N45°W 74.70

Surveyor's	Michigan	Liconea	No

85.82

83.34' 80.92