A.		\odot		\bigcirc		<i>9</i>		
City of	SURVE ZEMONUMEI Dearborn		,	\$ 7.00 DEF 8 DEC 95 S		PT# 6R		
Heights		LAND CORNI	ER RECORDATION CE	RTIFICATE REST 1.	arrighton, desiste	R OF DEFDS		
,,,,,,,,,,,	APR 0 5 1	996 Filing Requir	ement of Act 74, Mich	n. P.A. 1970	156年(中間7. 用。			
For corners i		_ ,			HONUMENTATION			
Wayne	COMMIS COUNTY)	SLOcated In:	Corner Code ##		28 451 PAGE	026		
1. Public La	nd Survey	т <u>2S</u> R <u>10E</u> т R	B-13	Co	ompliance with	1 2		
		T R			ON: 12-6-95-2	Per is		
		Ť R			ON: ITY REMONUMENTAT	<u>~</u> ~		
2. Property	=	T R		1	ROUP COMMITTEE	N		
in Sectio 3. Miscellan		T R				⊖		
Property		T R T R	WT Dr. and and delegan	Register of D	eeds Stamp & File	Number 07		
rioperty	III 360. 3	r n		L	40 Ar -			
4. Lot No	, Recorded	Plat		-				
				A B	CDEFGH			
				2 6	 			
_	••	-	- Han	3	 			
Lawrence R. I. Feindt in a field survey on November 30 19 95				4		11-12-		
Feindt	in a fie	ld survey on Nove		 				
			of 1970, the corner points me d rules therefore as require		17-1-16-1-15	4		
		•	tment of the Interior, Bureau	-1 1	 			
-	-		er points mentioned in lines 3	- 19	20 21 22	2324		
		•	of Land Surveyors or by a De monumented, recovered, f	91 1	 - - - - - - -			
expressed belo				1030	29 28 27-	2625-		
NOTE: Not	more than 4 corners, a	all in the same town ar	nd range, may be record	led 11				
on ti	nis certificate.			1231	32 33 34	35 36		
				13				
 A. Descripti 	on of original monume	nt and accessories and	d/or subsequent restorat	tion:				
B-13) 9	South 1/4 Corr	er of Section	31, T 2 S, R	10 E	1			
GENERAL LA		WAYNE COUNTY	BUREAU OF TAXATION	WAYNE COUNTY RO				
SET POST F	OR CORNER 6"-873 W-8 LINKS(5:	IRON .28') NE'LY-62.55'	-ELM	MONUMENT IN BOX NE'LY-130.78'-9	PIKE & TAG IN DE	POLE		
	-870 E-25 LINKS(16.	50') ENE'LY-100.0	00'-ED. POLE		IKE & TAG IN DE P			
DECEMBER 1		NW'LY-60.40' WNW'LY-86.80			'X" CUT IN CONCRET	E C/L		
BY: JOSEPH FLETCHER, DS WHW'LY-86.80'-ED. POLE				SW-75.16'-"X" C	SW-75.16'-"X" CUT IN SIDEWALK NW-59.49'-SPIKE & TAG IN DE POLE BY: B. YOUNG, SURVEY CHIEF			
			•					

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

/:Xi-

1935 11514

B-13) South 1/4 Corner of Section 31, T 2 S, R 10 E Distance to A-Found concrete monument in monument box. 13 measured 2641.48' (WPA = 2641.52'). measured 2630.36' (WPA = 2630.39'). Cor Distance to C-13 Corner was confirmed with irons found in "Rougelvania Subdivision No. 3" as recorded in Liber 61, Page 21 and "Dearbornshire Park as recorded in Liber 53, Page 97. Monument has been used as the north 1/4 corner of Section 6, T 3 S, 10 E (B-1) as documented by local plats and the WPA GLO notes and plat map indicate that a closing corner should be extant 20 links (13.2') west of B-13. No evidence of B-1 of T 3 S, R 10 E was found.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13) South 1/4 Corner of Section 31, T 2 S, R 10 E Found concrete monument in monument box at the intersection of Van Born Road and John Daly Road, and placed Wayne County brass disk stamped with license #21566 over iron road. Road surface is asphalt over concrete. Corner is accepted as a careful and faithful reestablishment of the position of the original corner. Witnesses:

N30°W - 59.31' - Found WCRC tag in southwest face of DE pole (rec. 59.49')

N65°E -130.68' - Found WCRC tag in southeast face of DE pole (rec. 130.78)

S34°E - 61.79' - Found WCRC tag in northeast face of DE pole (rec. 61.76')

\$35°W - 77.34' - Northeast corner of brick building (Church of God)

durence R. Jours W Date December 7, 1995 Surveyor's Michigan License No. 21566

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975