## RC 1146

FEB 28 1994

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

LI 25992 PA 830

|    | Wayne (County)                    | Located In:    | Corner Code =## |
|----|-----------------------------------|----------------|-----------------|
| 1. | Public Land Survey                | T 2S R 10E     | C-3             |
|    |                                   | T R<br>T R     |                 |
| 2. | Property Controlling in Section   | S T R<br>S T R |                 |
| 3. | Miscellaneous<br>Property in Sec. | S T R<br>S T R |                 |

Compliance with ACT 345, P.A. 1990

APPROVED ON: 11-30-93 DP. WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

| 4. | Lot No         | , Recorded Plat |  |
|----|----------------|-----------------|--|
| =  | Brivata Claima |                 |  |

For corners in

Lawrence R. October 25 : Feindt , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Courl of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-3) Corner Common to Sections 5, 6, 7 & 8, T 2 S, R 10 E GENERAL LAND OFFICE SET POST FOR CORNER WAYNE COUNTY BUREAU OF TAXATION

BEECH 12"-824 W-9 LINKS(5.94') BEECH 12"-N89 E-40 LINKS(26.40')

DECEMBER 22, 1816

BY: JOSEPH FLETCHER. DS

CROSS SE'LY-66.22'-SUB. COR. SW'LY-84.50'-IRON

NW'LY-69.45'-30" ELM

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<u>C-3) Corner Common to Sections 5, 6,</u> 7 & 8, T 2 Found 1/2" iron rod in monument box 12"± deep. Distance to B-3 measured 2624.71' (WPA = 2624.98'). Corner was confirmed with irons found in "Valley View Subdivision" as recorded in Liber 74 of Plats, Page 70; "Annis Hawthorne Manor Sub." as recorded in Liber 54 of Plats, Page 61, Wayne County records; and "Frischkorn's Golfdale Quarter Acres Subdivision" as recorded in Liber 48, Page 14, Wayne County records.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3) Corner Common to Sections 5, 6, 7 & 8, T 2 S, R 10 E Found 1/2" iron rod in monument box 12"± deep, and is accepted as a careful and faithful reestablishment of the position of the original corner.

N62°W - 83.06' - SE bolt of steel light pole #S40DD389

N39°E - 77.95' - Found PK nail with WCRC disk in SE face of utility pole S57°E - 65.09' - Found PK nail with WCRC disk in SW face of utility pole

S41°W - 63.80' - Found PK nail with WCRC disk in SE face of utility pole and

affixed Wayne County brass disk stamped with licence #21566.

| Signed by $\_$ | Laurence R. | Jour de |  |
|----------------|-------------|---------|--|
|                |             | _       |  |

Date November 29, 1993

Witnesses: