F 7	Sec.		NOT	NA
		Later of the later	U 10 -44	

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

or corners in		······································	1		
WAYNE (County)	Located In:	Corner Code #	Liber-30855 Page-2 99593134 12/29/1999		
. Public Land Survey	T <u>2S</u> R <u>10E</u> TR	<u>C-5</u>	F.E. Youngblood. Wayne Co. Register	of Deeds	
	TR TR		Compliance with ACT 345, P.A. 1990	nΩ.	
2. Property Controlling	S TR			NII.	
in Section 3. Miscellaneous	S T R S T R		APPROVED ON: 12-9-99 WAYNE COUNTY REMONUMENTA	TION	
Property in Sec.	S T R		PEER GROUP COMMITTEE		
			Register of Deeds Stamp & File I		
			ABCDEFGHIJ	K L M	
	orded Plat		2 6 5 4 3 2	1-	
			1 2 2 10 11	12	
, LAWRENCE R. FEIND I do hereby state that under requ	, in a field survey airements of P.A. 74, Michigan I	on <u>December 2</u> , 199 P.A. of 1970, the corner po	9 <u>9</u> Dints 5		
	ove were in conformance with re survey instructions of the United S	_	0 18 1/ 19 19 14	13	
Bureau of Land Management or	by a decree of a Court of Law	and for that the corner po	pints 7		
	pove were in conformance with the e of a Court of Law; establishe	-	ited,	24	
recovered, found as expressed be	low:		9 10 30 29 28 27 26	25	
NOTE: Not more than 2 cor	mers, all in the same town and	I range, may be recorded	11		
on this certificate.			12 31 32 33 34 35	36	
	onument and accessories and/o		13		
GENERAL LAND OFFICE		Y BUREAU OF TAXATION	MICH DEPT OF TRANSPORTATION		
Set Sec. corner B. Ash 12" S30°E 12 Lks	Cross (7.92') NE'ly - 84.15' -	Iron (EOLIND)	Nov. 8, 1977 By: Ervin P. Miller Mushroom Head Iron in monument box		
Elm 30" N74°W 22 Lks (14.52') SE'ly - 13.05' - 1	X in MH Ring (GONE)	N50°E - 70.92" -Traffic/light pole (FOU		
December 21, 1816 By: Joseph Fletcher		Tel. Pole (GONE) -Fire Hydrant (FOUND)	\$35°E -72.03' - Traffic/light pole (FOU \$45°W - 71.70' - Traffic/light pole (FO		
by. Joseph Fletcher	144V 19 - 03.73 -	ine riyulani (i Oorio)	N40°W - 76.61' - Traffic/light pole (FOI		
B. Description of corner evi C-5 CORNER COMMON TO S	dence found and/or method ap SECTIONS 7, 8, 17 & 18 T2S	plied in restoring or reesta 5-R10E	blishing corner:		
was confirmed with in "CONLEY'S FORD-GULLEY	cons found in "CUMMING	S FORD ROAD SUB'N" orded in Liber 55 P	Road and Beech-Daly Road. Cor as recorded in Liber 53 Page age 50; comparisons to WPA su	79	
Distance to corner D- Distance to corner B-	-5 Measured 2646.94' (-5 Measured 2640.13' (WPA = 2646.90' PLA WPA = 2640.04' PLA	T = 2647.56') T = 2640.00')		
C-5 CORNER COMMON TO S Found 1 1/2" rod in r	SECTIONS 7, 8, 17 & 18 T2S monument box in concre ner is accepted as a c	<u>-R10E</u> ate pavement at the	ocating the position of the corner: e intersection of Ford Road and reestablishment of the Desi	tion	
N45°E 84.01' Found 3/ S39°E 72.00' Found na S42°W 71.69' Found na	ail & MSHD tag in SE s /4" iron pipe (R=84.15 ail & MSHD tag in NE s ail & MSHD tag in SE s	5') side utility pole (side utility pole (Le (R=70.92') Lawrence R R=72.03')	6 ± * * # # #	
N44°W 76.58' Found na N39°W 83.87' Top of	ne County Remon disk a ail & MSHD tag in NE s fire hydrant (R=83.75'	side utility pole (')	R=76.61') 21566		
Signed by	neure R. Deur		Date <u>December 9, 1999</u>		
Surveyor's Michiga	n License No.		THE BOARD OF PROFESSIONAL SURVEYORS. JAN.		

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995