a moderation

For	corners	in	

Property in Sec.

	Wayne (County)	Located In:	Corner Code ##
t.	Public Land Survey	т <u>2S</u> r <u>10</u> E	E-3
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
2	Missollanasus	C + D	

Т

R

Compliance with ACT 345, P.A. 1990

APPROVED ON: 11-70-93 DO WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number


___ , Recorded Plat _ Private Claims _

Lawrence R. Feindt

November 3 _ , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

E-3) Corner Common to Sections 4, 5, 8 & 9, 10

GENERAL LAND OFFICE SET POST FOR CORNER
W.O. 16"-S63 W-48 LINKS(31.68') MAPLE 12"-846 E-26 LINKS(17.16') DECEMBER 23, 1816 BY: JOSEPH FLETCHER, DS

WAYNE COUNTY BUREAU OF TAXATION IRON

NE'LY-76.90'-ED. POLE

SW'LY-60.32'-ED. POLE NW'LY-55.96'-ED. POLE

FOUND 1" IRON IN MONUMENT BOX 855 E-72.56'-CHISELED "X" ON SW BOLT IN

CONC. LIGHT BASE N45 W-68.08'-TOP CENTER OF FIRE HYDRANT

N60 E-62.10'-POWER POLE WEST -65.92'-RAILROAD SPIKE IN PAVEMENT JULY 27, 1982

BY: MYRON L. PETRIE, PS #19841 MICHIGAN DEPARTMENT OF TRANSPORATION RECORDED IN LIBER 21484, PAGE 723, WCR

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-3) Corner Common to Sections 4, 5, 8 & 9, T 2 S, R 10 solid iron rod in monument box. Distance to D-3 measured 2653.95' (WPA 2653.75'). Corner was confirmed with irons found in "Conley's Warren-Telegraph Subdivision No. 1" as recorded in Liber 52, Page 58, Wayne County records and "Conley's Warren-Telegraph Subdivias recorded in Liber 51, Page 71, Wayne County sion" records.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3) Corner Common to Sections 4, 5, 8 & 9, T 2 S, R 10 E

Found 1" solid iron rod in monument box at the intersection of Warren Avenue and Telegraph Road, and is accepted as a careful and faithful reestablishment of the position of the original corner.

Witnesses:

Surveyor's Michigan License No. ___

68.06' - "X" cut in bolt top of fire hydrant N54°W -

62.15' - Found MDOT tag and nail in NW face of utility pole and affixed Wayne County brass disk with PK nail stamped with license #21566

below MDOT tag

70.32' - NW bolt of steel light pole #S40DA445

 $S46\,^\circ W$ - $44.82\,^\prime$ - Set "X" cut in top of curb $N81\,^\circ W$ - $297.88\,^\prime$ - Found WCRC bench mark disk

21566

___ Date November 29, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975