LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

u compa

| City | of | Dearborh 3 199 | O |
|------------|------|----------------------|---|
| For corner | s in | 6 4h 1 45 0 40 0 4 . | |

COMMISSION

Corner Code ##

\$ 1.00 RUMARITATION

LIBER 28451 PAGE 030

Compliance with ACT 345, P.A. 1990

APPROVED ON: 12-6-95 WASSE COUNTY REMORDMENTATION TOTAL COOKER CONTRACTOR

Register of Deeds Stamp & File Number

Wayne (County) Located In: T 2S R 10E E-11 1. Public Land Survey T _____ R ____ T _____ R ___ T _____ R __ 2. Property Controlling _ T _____ R __ S ____ T ___ R ___ S ___ T ___ R ___ in Section Miscellaneous Property in Sec.

__ , Recorded Plat __

5. Private Claims _

Lawrence R.

October 22 _ , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

-11) Corner Common to Sections 28, 29, 32 & 33, T 2 S, R 10 E

GENERAL LAND OFFICE SET POST FOR CORNER WAYNE COUNTY BUREAU OF TAXATION CROSS NE'LY-46.00'-TELEPHONE POLE

BLACK OAK 20"-N61 W-6 LINKS(3.96')
WHITE OAK 6"-342 E-27 LINKS(17.82') **DECEMBER 22, 1816** BY: JOSEPH FLETCHER, DS

SW'LY-69.15'-EDISON POLE NW'LY-34.40'-MANHOLE COVER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11) Corner Common to Sections 28, 29, 32 & 33, T 2 S, R 10 E No direct evidence of corner was found. Corner was re-established from property irons found in "Dearborn Park Subdivision" as recorded in Liber 33, Page 32; and "Dearborn-Telegraph-Subdivision" as recorded in Liber 51, Page 19. Distance to D-11 measured 2629.30' (WPA=2629.58').



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11) Corner Common to Sections 28, 29, 32 & 33, T 2 S, R 10 E Set railroad spike in the center lines of North bound lane of Telegraph Road and Carlysle Road surface is concrete with asphalt overlay. The selected location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Witnesses:

N45°E - 56.51' - SW corner of bank building

S39°E - 40.91' - Set PK nail in top of concrete curb and affixed Wayne County brass disk stamped with licanse #21566.

 $S58\,^\circ W$ - 71.92' - Set chiseled "X" in SE corner of traffic signal pole base $N59\,^\circ W$ - 70.68' - Set chiseled "X" in SW corner of traffic signal pole base

Date

N37°E - 50.00' - Set T-iron & #21566 cap drilled in concrete walk

S37°W - 50.00' - Set concrete monument with brass disk stamped with #21566

Lawrence R. Down W Surveyor's Michigan License No. 21566

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983