SURVEY & REMONUMENTATION

RC 1569

\$ 13.00 MISCELLANEOUS RECORDING 28 DEC 94 8:22 A.M. RECEIPT# 128 RECORDED

APR 2 5 1995

LAND CORNER RECORDATION CERTIFICATE MEST E. YELFANDON, REDISTER OF DEEDS Filing Requirement of Act 74, Mich. P.A. 1970

WAYNE COUNTY, HI

For corners (COMMISSION) Wayne Located In: Corner Code ≠#	L127800PA061
1. Public Land Survey T 3 S R 8 E B-11 T R R T R T R T R T R T R T R T R T R	Compliance with ACT 345, P.A. 1990 APPROVED ON: 12-8 94 70-7 WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE
2. Property Controlling in Section S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L 2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	5 6 -18 -17 -16 -15 -14 -13 - 7 8 -19 -20 -21 -22 -23 -24 - 9 10 -30 -29 -28 -27 -26 -25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: B-11) South Corner Common to Sections 30 and 31, T.3 S.,R.8 G.L.O. (1830's) J. Wampler set corner witnesses: Ash 4 N. 6 55 W. 18 (gone) W.P.A. (1930's) found iron, witnesses: N.W. 56.76 power pol Elm (gone), S.E. 40.24 W.C.C. sign post (gone), N.E. 87.04 5 5" Elm (gone) No R.C.'s or C.S.'s on file at Wayne County Reg. of Deeds.	0 E. 4 (gone) W.O 45. e (gone), S.W. 71.88 5" " Elm (gone), N.E. 87.04
B. Description of corner evidence found and/or method applied in restoring or reestablish B-11) South Corner Common to Sections 30 and 31, T.3 S.,R.8 Found a 1" iron pipe with steel bar & cap #19836 and 18633. comparing to W.P.A. section measurements: B-11 to A-11 Record = 2770.29 Measured = 2769.98 B-11 to C-11 Record = 2654.91 Measured = 2654.11 Angle line B-11 & C-11 to B-11 & A-11 Record = 179° 11' 35" Also found the following witnesses: Found nail East face 6" Elm N.27° E. dist. = 31.90 Found nail East face 8" Hickory S.23° W. dist. = 35.25	E. Verified corner by Measured = 179° 11' 35"
C. Description of monument for corner and accessories established to perpetuate locating B-11) South Corner Common to Sections 30 and 31, T.3 S.,R.8 Found a 1" iron pipe with steel bar & cap #19836 and 18633. The selected location is accepted by the Contractor and is good professional surveyors as the best available evidence of the Witnesses: Set nail & WCR tag East face 6" Elm N.27° E. dist. = 31.63 Set nail & WCR tag East face 6" Elm due North dist. = 35.5 Set nail & WCR tag East face 6" Elm due North dist. = 28.95 Set steel bar traverse iron due East dist. = 258.01 Set nail & WCR tag S.E. face 8" Elm N.45° E. dist. = 19.97 Placed Wayner County Remondmentation brass marker stamped with the second state of th	generally accepted by e position of the original corn .05 th #10705 WHIMALLY REPORTS