## RC 1352

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LI27042PA374

Compliance with ACT 345, P.A. 1990

APPROVED ON: 12-15-93 1951.
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

For corners in WAYNE County: ROMULUS TOWNSHIP #13 Corner Code # Located in: 1. Public Land Survey 3 S 2. Property Controlling in Section 3. Miscellaneous Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims Kenneth S. Wilkerson , in a field survey on October 28 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Set Post - GLO - NO GLO WITNESSES REMAIN Fd. Iron - B of T L-11 Fd. WCRC mon. box, L. 20202, P. 596 - 06/23/78 NE 43.40 X in S end of Hdwall Se 69.33 tag in SW face PP SW 64.77 tag in SE face PP NW 52.06 X in N end of Hdwall B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. L-11 Fd. 1/2" rod in mon. box

F	<u> </u>	B (	ן כ	) I	Ξ Ι	= (	3 H	<b>-</b> 1	١،	1	< 1	_ 1
2	- (		- 5	[	_ 4	ļ .	3		_ 2	_	_ 1	-
3		Н										
4	_ •	-	<u> </u>	-	<u> </u>	-	-1	0-	<b>— 1</b>	1 —	-1	2—
5												_
6	_1	I 8 —	1	ן 7	1	l 6 –	t	5 	_1	4 <b>—</b>	L 1	। 3—
7										Ĺ		Ĺ
8	_ 1	 9	2	ე	_2	 1 _	L	2-	2	! 3—	_2	 4 –
9		Ľ		<u> </u>	<u></u>	<u>'</u>		Ĺ		Ľ		Ľ.
10	_ a	  0_	_ ,	9 —	_ ,	 8	ر _	7	2	 6 –		 '5
11	_ `	ĭ	٦	j —	Γ'	Ĭ	Γ-	, İ		Ĭ		Ľ
12	_3		-	2 —	٦,	3-	Γ,	14_	_3			6-
16	<u>ا</u> ع	'' –	٦,	– ۲	۲	ა <del>-</del> .	J	4 — 	<u>ا</u> ع	Ÿ-	٦,	o

FOREST E. YOUNGBLOOD REGISSES CHOREDS WE'NN FOR WITH MJ

- SW 64.78 WCRC tag in SE face UP
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
  Set WC remonumentation washer and OHM KSW 21584 cap on iron.
  - L-11 N 30 E 74.86 Top nut on hyd. S 21 E 69.24 WCRC tag in SW face PP S 39 W 64.68 WCRC tagin SE face PP N 15 W 67.25 WCRC tagin SW face PP

NE 50.33 edge of san MH SE 69.28 WCRC tag in SW face UP

The selected location is accepted as the best evidence of the original corner.

Signed by Signed

Drafted By: Kenneth S. Wilkerson Surveyor's Michigan License No.

Orchard, Hiltz & McCliment, Inc. 34935 Schoolcraft Road \* Livonia, Michigan 48150 \* Phone: (313) 522-6711

Date: \_

FORM APPROVED BY MEHICAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

> ar 11KD