FILE DO BOT	LAND CORNER R	ECORDATION CERTIF	FICATE		
For corners in	i mið Hedamenia	HE OF MEL 14, MICH. P.A	Liber-3	0836 Page	e-37
WAYNE	Located In:	Corner Code #	9959084 F.F. Youngh	lood, Wayne Co. Regi	วว ster of Deeds
(County)	SUMPTER	OTAME COULD II	RDANDSY	/L	
1. Public Land Survey	T <u>4S</u> R 8E TR	A-7		Compliance with ACT 345, P.A. 1990	P.
 Property Controlling in Section Miscellaneous Property in Sec. 	TR TR STR STR STR STR		WAYNE CO PEE	ED ON: 12-10-9 OUNTY REMONUMEN OR GROUP COMMITTE ds Stamp & File Num	TATION E
4. Lot No. Recor	rded Plat		ABCDE	FGHIJK	L M
I, STEVEN E. DUNN, in a that under requirements of P.A. 74 1 and 2 above were in conformar current manual of survey instructic Land Management or by a decree lines 3, 4 and 5 above were in	a field survey on February 15, It, Michigan P.A. of 1970, the comer process of the United States Department of of a Court of Law and for that the corconformance with the rules of the M. Court of Law, established, re-established,	1999, do hereby certify oints mentioned in lines sefore as required in the f the Interior, Bureau of ner points mentioned in lichigan Board of Land	2 6 5 5 5 6 18 17 7 8 19 20 9	- 4 - 3 - 2	
range, may be rec	corners, all in the same town corded on this certificate.		10 30 29	-28 - 27 - 26	25-
A. Description of original mo	nument and accessories and/or sub	sequent restoration:	12 31 -32 -	-3 + 3 + 35 + 1 × 2 h	-36 Orl
GLO POST-NO EVIDENCE OF	ORIGINAL CORNER FOUND. SUF	RVEYED BY ALEX HOLMES-	1816	√see \$10€ €	
WPA RE-SURVEY OF ORIGINA	AL SECTIONS			1930'SECTION	•
WAYNE COUNTY BUREAU OF	TAXATION	TIES TO SECTION COR	RNERS #91	1930's	
WAYNE COUNTY BUREAU OF WAYNE COUNTY BUREAU OF		1/2 SECTION MAP-NW C 1/4 SECTION MAP-SW C	OF 18	SEPTEMBER 5, 1952 JULY 27, 1970	
BOARD OF WAYNE COUNTY F	ROAD COMMISSIONERS	SECTION CORNER WIT	INESS RECORD #91	MARCH 8, 1972	OF MICH
<u>L.C.R.C.:</u> L.20551, P.446	Daniel Sandomierski #24616	Found P.K. Nail in road.		MARCH 8, 1972 JUNE 22, 1979	OF MICA
WAYNE COUNTY BUREAU OF	TAXATION	1/4 SECTION MAP-SW	OF 18	1983	DUNN PROFESSIONAL SURVEYOR
DEPARTMENT OF MANAGEMENT AND BUDGET ASSESSMENT AND EQUALIZATION DIVISION:			% SECTION MAP-NW of 19 1990 No. 2840		No. 28408
B. Description of corner evider A-9 Section corner. Corner	nce found and/or method applied in not common with M-7, T.4S., R.7E.	restoring or reestablishing c	orner:	90000	ROFESSIONAL
Found 3/4" Iron Pipe in Monumen	nt Box in asphalt road at centerline o	f Rewsonville Road and south	of Tallady Road. Corner		
I verified the location by comparir	ng field measurements with record n	neasurements of WPA Re-Sur	vey of Original Sections.		
FIELD MEASUREMENTS & RECORD MEASUREMENTS: A-7 to A-8 A-7 to B-7 WPA Re-Survey-2645.34' Field-2645.23' GLO-46 chains (3036.00') WPA Re-Survey-3083.09' Field-3082.95		A-7 to M-7 (T.4S., R.7E.) GLO-1 chain, 36 links (89.76') WPA RE-SURVEY-80'± Field-95.99'		Angle B-7/A-7/A-8 89°58'25" WPA Re-Survey 89°58'20" Field	
C. Description of monument for A-7 Section corner. Not a co	or corner and accessories established	d to perpetuate locating the p	osition of the corner:		
I REPLACED THE FOUND 3/4" 28408" IN EXISTING MONUMEN	IRON PIPE WITH A 1/2" BY 18" IR NT BOX IN ASPHALT ROAD. NOT	ON ROD WITH ALUMINUM O A COMMON CORNER.	CAP STAMPED "WAYNE	ECOUNTY REMONUM	ENTATION
WITNESSES: Az. 90° 24.25' Az. 150° 81.30' Az. 203° 83.41' Az. 205° 67.47' Az. 305° 58.34' Az. 0° 95.99' THE SELECTED LOCATION IS EVIDENCE OF THE POSITION IS	Found 60d nail on southeast side Set PK nail and Wayne County R. Found Iron Pipe in Monument Bos ACCEPTED BY ME AND IS GENE	emonumentation witness tag o emonumentation witness tag o of 18" tree. emonumentation witness tag o rin asphalt road. (M-7, T4S, R	n southeast side of utility n southeast side of utility 7E)	pole.	
Signed by Starra C		Nata	Du 21.1	<i>/ 4 4 4</i>	

R LCR 9 HR 1Pg ADPJ

Surveyor's Michigan License No. 28408