LAND CORNER RECORDATION CERTIFICATE h. P.A. 1970

REMONUMENTATION \$ 4.00 \$ 7.00 DEED 26 DEC 96 12:43 P.M.

RECET

EDS

	Filing Requirement of Act 74, Mich
For corners in	•

FOREST E. YOUNGBLOOD, REGISTER Located in: Huron Corner Code # MAYNE COUNTY, MI Township R 9E

RECORDED

APPROVED ON: DEC WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number

Recorded Plat **Private Claims**

R

in a field survey on <u>Randy Kolehouse</u> <u>December 5</u> do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE:

M-6

WAYNE

Public Land Survey

Property Controlling

in Section

Miscellaneous Property in Sec.

> Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1817	G.L.O.	Fletcher	Notes		Post
1930's	WPA Notes	N/A	Section Map and Ties		Iron
1973	W.C.R.C.	Coon	Witness Record	7	1" Iron Pipe
1974	Cert. Survey	Stanley #12031	L. 18794 P. 358-363		Iron Pipe
1974	Cert. Survey	Stanley #12031	L. 18968 P. 139-141		Iron Pipe
1978	L.C.R.C.	Soderberg #17635	L. 20523 P. 755		Conc. Mon. in Box
1987	Cert, Survey	Crossman #9428	L. 23282 P. 879-881		Conc. Mon. in Box

Records indicate this corner is common with A-6 T4S R10E.

- R Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-6 Found a concrete monument in a monument box 3' East of the C/L of Inkster Road (asphalt) running North and South that checks one remaining WPA witness and also checks the following witnesses:

WPA Notes (1930's)

D.E. Pole SW 118.05' (m. 118.56')

W.C.R.C. Witness Record (1973) Nail NW Face MBT Pole NE 125.68' (m. 125.80') Nail SW Face MBT Pole SE 118.00' (m. 118.56') NE Corner House SW 103.25' (m. 103.12')

Nail N Face D.E. Pole W 31.74' (m. 31.69')

L.C.R.C. L. 20523 P. 755 (1978) Nail & Tag in D.E. Pole West 31.71' (m. 31.69') P.K. Nail D.E. Pole SE 118.55' (m. 118.56') E. Edge Asphalt 12.25' (m. 12.3')

Cert. Survey L. 23282 P. 879-881 (1987) W.C.R.C. Nail & Tag NW Side Util. Pole N 55° E 126.0' (m. 125.80') P.K. W Side Util. Pole S 20° E 118.60' (m. 118.56') W.C.R.C. Nail & Tag S Side D.E. Pole S 15° W 159.18' (m. 159.16') W.C.R.C. Nail & Tag N Side D.E. Pole N 80° W 31.71' (m. 31.69')

Measure North to M-5 = 2617.91' (WPA = 2618.0') (G.L.O. = 2640.0') Measure South to M-7 = 2619.85' (WPA = 2619.6) (G.L.O. = 2640.0')

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-6 Set brass "Wayne Co. Remon." disk and survey cap #25854 on an existing concrete monument in an existing monument box.

Nail w/W.C.R.C. Tag in W Side MBT Pole N 17° E 125.80' P.K. Nail in NE Side 12" Poplar S 56° E 61.51' P.K. Nail in W Side MBT Pole S 09° E 118.56'

Nail w/W.C.R.C. Tag in E Side P. Pole S 16° W 159.16'

Corner of House(?) #21592 S 84° W 103.12' Nail w/W.C.R.C. Tag in N Side P. Pole N 80° W 31.69' Nail w/W.C.R.C. Tag in W Side MBT Pole N 17° E 125.80' East Edge Asphalt 12.3'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Signed by 25854 Surveyor's Michigan License No

MICHIGAN RANDY L KOLEHOUSE LAND

SED LAND &

of

SURVEYO