DEC 0 2 1993

RC 1109

COMMISSIO		NER RECORDATION CERTI	いんひひひ	1 pa 740
For corners in	Filing Requ	irement of Act 74, Mich. P.	A. 1970	
Wayne (County)	Located in:	Corner Code ##		
Public Land Survey	T R T R	T 4S R 10E 1-7 Compliance with T R ACT 345, P.A. 1990 T R APPROVED ON: 10 - 28 - 9 3 5 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7		90
2. Property Controlling	T R S T R		WAYNE COUNTY REMONUN PEER GROUP COMM	ADMAINTHOIA
in Section 3. Miscellaneous	S T R S T R		, , , , , , , , , , , , , , , , , , , ,	
Property in Sec.	S T R		Register of Deeds Stamp	& File Number
4. Lot No	, Recorded Plat			
5. Private Claims				G H I J K L
			2 - 6 - 5 - 4 -	+-3-+-1-
			4 7 8 9	10 11 12
I, Bruce Antcliff	, in a field survey onA	ugust 24 , 19 93		
in lines 1 and 2 above were current manual of survey in Management or by a decree above were in conformance	requirements of P.A. 74, Michigan P. e in conformance with regulations a structions of the United States Deport a Court of Law and/or that the conwith the rules of the Michigan Board, re-established, monumented, re-	and rules therefore as required in artment of the Interior, Bureau of Liner points mentioned in lines 3, 4 a d of Land Surveyors or by a Decrea	n the	22 23 24
NOTE: Not more than 4 on this certificat	corners, all in the same town te.	and range, may be recorded	11 32 33 32 33	34 35 36
A. Description of origina	al monument and accessories a	ind/or subsequent restoration:	13	
	Iron Ion. in Handhole (L 18719, P 813 I/2" Rod in Mon. Box)		
Mon. in Mon. Box	r evidence found and/or method x: measured to E1/4 S.22 & SE S ed well with WPA Surveys.	• • • • • • • • • • • • • • • • • • • •	iblishing corner:	
	·			2: 27 (元)
	ment for corner and accessories			er:
Set Wayne Coun	nty Remonumentation Marker and	Cap #25826 on existing monun	nent.	F MICH
Witnesses	`PC Tag SE Easo D.D. NE 70 60	N.	A STANLING	BRIJCE *

Nail & WCRC Tag SE Face P.P., NE, 79.60' Nail & WCRC Tag NE side P.P., SE, 77.25' Nail & WCRC Tag SE Face P.P., SW, 65.97' P.K. SW Face P.P., NW, 53.04'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Bruce Contali

25826 Surveyor's Michigan License No.

Date 11-10-93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

ANTCLIFF SURVEYOR No. 25826