REMONUMENTATION

MAY 1 0 2000

No. 39098

Bigned by

Burveyor's Michigan Li

LISTR

| SECTION | | IER RECORDATION CE irement of Act 74, Mich. | . P.A. 1970 |
|--|---|--|---|
| | Logated In- | Corner Code # | SEE SEE |
| WEXFORD COUNTY | Located In: | Comer Code # | |
| 1. Public Land Survey | T <u>21N</u> R_09W TR TR | G-2 | CEIVED -1 PN 3:07 REPO COUNTY MI |
| 2. Property Controlling S | T R T R | | = 0 |
| | TR | | |
| 3. Miscellaneous S Property in Sec. S | T R R T R | | Register of Deeds Stamp & File Number |
| 4. Lot No, Recorde | d Plat | | A B C D E F G H I J K L M |
| 5. Private Claims | | | 2 6 5 4 - 4 3 2 1 |
| I, George D. Smith, P.S., , in a firequirements of P.A. 74, Michigan P.A were in conformance with regulations instructions of the United States Dep decree of a Court of Law and /or that conformance with the rules of the Mi Law; established, re-established, monu- | a. of 1970, the corner po and rules therefore as red artment of the Interior, if the corner points mentio chigan Board of Land Su | ints mentioned in lines 1 and 3 quired in the current manual of Bureau of Land Management ned in lines 3, 4 and 5 above irveyors or by a Decree of a 6 | 2 above 5 |
| NOTE: Not more than 2 corners, all on this certificate. | in the same town and ra | nge, may be recorded | 10 30 29 28 27 26 25 |
| A. Description of original monum | ent and accessories ar | nd/or subsequent restoratio | |
| G-2) 1848 GLO subdivis Hemlock 12- | | S. Maple 9-N69½E-24, | 131 in 1 in Grands and the desire of the first |
| | ells, revised Plat of Cl ary Plat of east-west | am Lake Liber 1 of Plats, P | Page 1, |
| 1880 Plat of Cobb 1881 A. Teed Surv 1882 Plat of G.A. | s & Mitchells Addition | to City of Cadillac, Liber 1 Corner found, no description west 1/4, Section 3, by A. | I, of Plats, Page 5, plat shows quarter post. n or witnesses given. Teed, Liber 4 of Plats, Page 488. Plat indicates corne |
| 1882 Plat of G.A. | Mitchell Plat of South | west 1/4 Section 3 by A. 7 | Teed, Liber 1 of Plats, Page 1. Plat indicates corner is |
| 1907 D. Teed Note | es Liber 1, Page 4, no | description given, note add | ded in 1946 states Railroad rail 33' east under cement |
| walk. 1983 Ray PS #258 | 369 Certificate of Surv | vey, survey indicates west | 1/4 corner section, 15" 33' east of 1" pipe. |
| B. Description of corner evidence | e found and/or method | d applied in restoring or ree | stablishing corner: |
| show corner being in Section 3 projected v calculated by projecti Cadillac. This corner quarter corner comm | set corner 33' west of vesterly from center 1 ing 33' east from the is accepted as a care on to Sections 3 and 4 | of Southwest corner of the /4 along south plat line. T Northeast corner Lot 1, Blo ful and faithful re-establish 4, T21N, R9W. | Right-of-Way Map Project 83-3 for US-131 does not Plat G.A. Mitchell's Plat of the Northwest 1/4 of this position checks closely within 0.02' from position ock "A" Cobbs and Mitchell's Addition to City of iment of the position of the original corner being the |
| | | | locating the position of the corner: |
| G-2) Set Wexford County \$80W 54. N85W 51. N41W 54. West 33.0 | 75 Powerpo 11 "x" in to 57 36" Map | p concrete light pole base de | 3 1999 3/4. |
| | OCALA MARIA | | |
| GEORG * SMIT PROFESS SURVE | H E | | Peer Group Reviewed and Approved Date: 12 Nov 9 1 Eilen D. Wilcox, Wexford County Surveyor |

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 [REVISED JAN., 1983] REVISED OCT., 1995

Date 11-12-99