

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 21 N.R. 10W


Wexford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 25-36

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/31/61

WITNESSES TO CORNER.....



7" Cedar - S 20 E - 21.3 feet

5" Cedar - S 43 W - 17.8 feet

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division personnel during management work in this area. Found squared post at corner with both U.S. bearing trees in place, the SE with good face and marks plain. Very good original corner. Falls about 8 feet north of EW fence.

SURVEYOR'S SEAL

SIGNED Kenneth J. Oetting DATE 11/14/61  
REGISTERED LAND SURVEYOR