LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

MAY 2 0 1997

COMMISSION

Wexford (County)	Located In:	Corner Code #	RECEIVED
Public Land Survey Property Controlling in Section	T 21N R 10W T R T R T R S T R S T R	_M-7	1996 DEC 13 PM 3: 34 Linda Laughmillan WEXFORD COUNTY, MI REGISTER OF DEEDS
Miscellaneous Property in Section	s T R s T R		Register of Deeds Stamp & File Number
I, George D. Smith, do hereby certify that under requirements 1 and 2 above were in commanual of survey instructions Management or by a decree of 5 above were in conformance to Decree of a Court of Law; established the survey of the conformance of the court of the	in a field survey on Novem uirements of P.A. 74, Michigan P.A. of conformance with regulations and rules of the United States Department a Court of Law and/or that the corner with the rules of the Michigan Board olished, re-established, monumented, mers, all in the same town and ran	per 8 , 19 96 1970, the corner points mentitherefore as required in the curific of the Interior, Bureau of points mentioned in lines 3, 4 of Professional Surveyors or re-monumented, recovered, for	2 - 8 - 6 - 4 - 3 - 2 - 2 - 23 - 24 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 -
A. Description of original s	monument and accessories and/o	or subsequent restoration:	:

- M-7) 1837 GLO Quarter Section Post by John Brink, Deputy Surveyor, Elm 14 S 58° W 84, Elm 7 N 65 1/2° W 42
 - 1891 A.J. Teed Survey, Liber 1, Page 32, Corner found no description given, found 3 Gov. witnesses, W.Pine S 46 1/2° E 1.86
 - 1896 A.J. Teed Survey, Liber 1, Page 30, Corner is under crossway, drove large bolt in the crossway log over corner, put in witness post N 44° W 41 links S 52° W 41 links (FB 83 Page 7)
 - 1906 Survey by D.E. Teed found stake from H.L. Devoe, no witnesses given
 - 1960 WCRC Bk 40, Page 77, P.P. N 45° W 115.95' TP S 75° W 114.73', TP S 50° E 47.12', FP N 45 °E 45.86'
 - 1973 LCRC by J. Granger RLS # 16041, Liber 2, Page 608 set new county mon. 6" undergound P. Pole S 49° W 48.18', Corner fence post S 53° E 43.62' chisel mark (x) on conc. culv. N 33° W 35.63'.
 - 1974 Wilcox Associates, Certificate of Survey by J.L. Wilcox RLS #14102, Liber 1, Page 259, found Wexford County Mon. same witnesses as 1973 LCRC, Liber 2, Page 608
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found Wexford County Mon. as set by J. Granger, RLS 16041 did not accept position of corner, method applied in re-establishing corner not given on L.C.R.C. Set 5/8" x36" Iron with Wexford Co. brass cap stamped PS#39098, 1996 SE 13, in Mon. Box by single proportionate measure between found comers 1/2 mile North and South and in centerline of North-South Road. This position checks within 0.4' of A.J. Teed's 1/2 mile dist. to South and checks within 1.2 of D. Teed's distance to SW corner Sec. 13, and 1.35 to East 1/4 Section 13. This position is accepted as a careful and faithful re-establishment of the position of the original corner, being the section corner common to Sections 13 and 24, T21N, R10W and Sections 18 and 19, T21N, R10W.

Peer Group Reviewed and Approved

Richard D. Wilcox, Wexford County Surveyor

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-7) Set 5/8"x36" Iron with Wexford County brass cap stamped SE 13, 1996 PS 39098 in Mon. Box.

N42°W - 118.79' - Power Pole

N30°E - 65.68' - "X" on NE comer Box Culvert

S45°W - 40.72' - "X" on W. End 24" Conc. Cross Culvert

S55°E - 46.19' - Tele. Pole (cut-off)

SURVEYOR 39098 POFESSIO

GEORGE D

SMITH PROFESSIONAL

#39098 Surveyor's Michigan License No.