MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_22 NR_9.W__

- - -	wexford	COUNTY
Section corner	common to Sect	ions 14-15-22-23
MONUMENT##.	pipe with 4" b	rass cap
5" Maple	N3TR =	22½inks_
14" R. Oak -	3 51₩ -	22½ links
Marked for prev	ious NBT	
	MONUMENT 1". 5" Maple 10" R. Oak 14" R. Oak	Mexford Section corner common to Sect MONUMENT 1" pipe with 4" b 5" Maple - N31" - 10" R. Oak - S66E - 14" R. Oak - S51W - Marked for previous NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew white making a partial resurvey of this township. Found definate evidence (shredded wood and discoloration) of government post at corner. Stumps for both government BTs in place. Falls directly in line with old page wire fence south. A square stake, set within last 5 years, here \$150, faced by several blazed trees.

Corner was set and witnessed April 16, 1959.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR DATE 4/17/59