

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


WEXFORD COUNTY  
T 22 N R 9 W

DESCRIPTION OF CORNER Sec. corner common to Sections 23-24-25-26

CORNER MONUMENT Found 1 1/4" pipe in Mon. box in approximate ctr of E-W blacktop Co. Road

DATE MONUMENT PLACED AND WITNESSED 4-26-71

WITNESSES TO CORNER..... 3 1/2" Oak N 81 W 116.8'



7" R. Pine N 29 E 57.7'

5" J. Pine S 33 E 61.1'

AND

Cedar Post & location tag Due N 33.0'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1 1/4" pipe in monument box in approximate center of E-W blacktop county road. This corner was originally recovered in 1958 by Ken Ostling, DNR Surveyor, at a position as shown him by Morn Sageman, former Wexford County Road Engineer. The monument box was placed around the pipe sometime between 1959 and 1970, probably when the gravel road was black topped.

SURVEYOR'S SEAL

SIGNED

*Carl F. Row*  
REGISTERED LAND SURVEYOR

DATE

5-3-71

DISTRIBUTION:

12028

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68