STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		_1	WEXFORD			COUNTY	
		T	22	M	R _	9	H
DESCRIPTION OF CORNER	N 1/16 corner come	n to Section	ns 23 -	- 24			
CORNER MONUMENT	Set 1"x36" Pipe 6 (edar Guard	post w/	locat	ion 1	tag.	
DATE MONUMENT PLACED AN	D WITNESSED	4	-27-71				
WITNESSES TO CORNER	. Power Pole	N	80 E		, <u> </u>	5.7	8'
N	20" Oak	K .	68 W		<u> </u>	75.6	•
28	14" Oak	<u>u</u>	71 E	·	 	43.4	•
	AND						
CIRCLE CORNER REGISTE	RED				•		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established equidistant and on line between Section corner to North and 1/4 corner to South, during a retracement survey in this area.

SURVEYOR'S SEAL

CICNED

PECTOTERED LAND CURITYON

5-4-7

DISTRIBUTION:

ISTERED LAND SURVEYOR

12020

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing