


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY
T 22 N R 9 W

DESCRIPTION OF CORNER Sec. corner common to Sections 21-22-27-28
CORNER MONUMENT Found 1 1/4" pipe in Mon. Box in E-W blacktop road
DATE MONUMENT PLACED AND WITNESSED 4-26-71
WITNESSES TO CORNER..... 22" Oak N 29 W 95.9'



22" Maple N 12 E 118.4
Power Pole S 41 E 50.9'
AND Cedar post w/location tag Due N 33'
Fence to North Due E 6'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner, being a 1 1/4" pipe, was recovered by the MSHD in 1964. They recovered the corner as recovered by Norm Sageman, former Wexford County Rd Comm Engr.

SURVEYOR'S SEAL

SIGNED *Carl F. Roeder* DATE 5-6-71
REGISTERED LAND SURVEYOR 12028

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing